6. In case of fire

















DO NOT SUBMERGE VEHICLE TO EXTINGUISH/COOL BATTERY FIRE



USE COPIOUS AMOUNTS OF WATER



POSSIBLE BATTERY RE-IGNITION!

MONITOR HV BATTERY TEMPERATURE FOR AT LEAST 24 HOURS

7. In case of submersion

Treat a submerged Model 3 like any other submerged vehicle. Wear appropriate PPE for water rescue. Remove the vehicle from the water and continue with normal high voltage disabling. Vehicles submerged in salt water should be handled with a greater potential risk of an HV battery fire. Tilt the vehicle to back and forth to allow water to drain out and store flat.

8. Towing / transportation / storage

Use a towing truck with flatbed.

NO towing with running traction wheels.







WARNING POSSIBLE BATTERY RE-IGNITION! AFTER A FIRE INCIDENT, STORE OUTSIDE AT A SAFE DISTANCE (50 FT/15 M) FROM OTHER VEHICLES AND STRUCTURES!

9. Important additional information

First Responders and Second Responders with emergencies, call Tesla Roadside Assistance. Refer to https://www.tesla.com/support/roadside-assistance for the applicable hotline number.

First responder information can be found at https://www.tesla.com/firstresponders. First responders and training officers who have questions, contact firstrespondersafety@tesla.com.

Airbags



Knee airbags are only installed in North America and South Korea.

10. Explanation of pictograms



In some working environments, the Infrared (IR) device is referred to as a Thermal Imaging Camera (TIC).

TESLA MODEL 3 From 2020 — Present	ID No.	Version No.	Page No.
	TESLA-202012-001	01	04/04