## **UUT Report**

**Station ID: IT-W-7303101** 

Serial Number: NONE

Date: giovedì 30 marzo 2023

Time: 14:02:57
Operator: ITLAVIT1

**Execution Time:** 00:05:33.063

Number of Results: 355 UUT Result: Passed

**Begin Sequence: MainSequence** 

(C:\Users\itlavit1\OneDrive - ABB\LabRnD\_Shared\TestStand\Sequences\M4M\PMD-1803.seq)

DUT recap		
Status:	Done	
TestResults/Data:		
Serial Number:	Q032AB102T	
Type Designator:	M4M30SMA	
FW Version:	P3.0.0.3	
PMD-1803		
Status:	Passed	
Module Time:	333.536	

Begin Sequence: PMD-1803

(C:\Users\itlavit1\OneDrive - ABB\LabRnD\_Shared\TestStand\Sequences\M4M\PMD-1803.seq)

Touch Reset Notifications - Init	
Status:	Passed
Module Time:	38.6861

**Begin Sequence: TouchResetNotifications** 

(C:\Users\itlavit1\OneDrive -

ABB\LabRnD\_Shared\TestStand\Sequences\M4M\PMD-1803.seq)

Touch - Go Home	
Status:	Passed
Module Time:	18.8774

Begin Sequence: Touch\_GoHome (C:\Users\itlavit1\OneDrive -

ABB\LabRnD\_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

### **End Sequence: Touch\_GoHome**

Touch - Reset Notifications	
Status:	Passed
Module Time:	19.6679

### **End Sequence: TouchResetNotifications**

Touch Init WithCheck		
Status:	Passed	
Module Time:	39.5336	
Pass/Fail Touch_IsWorking		
Status:	Passed	
Touch Init WithCheck		
Status:	Passed	
Module Time:	39.366	
Pass/Fail Touch_IsWorking		
Status:	Passed	

Check Warnings Increment	
Status:	Passed

Touch - Go Home - Read Warnings		
Status:	Skipped	
Touch - Go To Warnings Shortcut - Read Warnings		
Status:	Passed	
Module Time:	6.92238	
Touch - Go Home - Read Warnings		
Status:	Skipped	
Touch Reset Notifications		
Status:	Passed	
Module Time:	38.8234	

# Begin Sequence: TouchResetNotifications (C:\Users\itlavit1\OneDrive - ABB\LabRnD\_Shared\TestStand\Sequences\M4M\PMD-1803.seq)

Touch - Go Home	
Status:	Passed
Module Time:	19.0008

Begin Sequence: Touch\_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD\_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	

Status:	Passed
---------	--------

### **End Sequence: Touch\_GoHome**

Touch - Reset Notifications	
Status:	Passed
Module Time:	19.6783

#### **End Sequence: TouchResetNotifications**

Touch - Go Home - No Warnings	
Status:	Passed
Module Time:	19.0575

Begin Sequence: Touch\_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD\_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

**End Sequence: Touch\_GoHome** 

Touch - Go To Warnings - No Warnings		
Status:	Passed	
Module Time:	7.82183	
Touch - Go Home - No Warnings		
Status:	Passed	
Module Time:	19.1286	

Begin Sequence: Touch\_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD\_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

**End Sequence: Touch\_GoHome** 

Check Warnings Num = 1	
Status:	Passed

**End Sequence: PMD-1803** 

**End Sequence: MainSequence** 

# **End UUT Report**