UUT Report

Status:

Station ID: Serial Number: Date: Time: Operator: Execution Time: Number of Results: UUT Result: Product: Product: Product type: Comm type: Product FW Version: Comm FW Version:	IT-W-7303101 NONE lunedì 27 noven 17:09:21 administrator 18.6706709 sec 38 Terminated ARI LV ARI LV COMM1_RS485 56010809 56010000		
Begin Sequence: Main		 red\TestStand\Sequences\MC	DD\FMEA.seg)
	· -		(I FILA.Seq)
	d Switch1 closed - Switch	2 open - before command	
Status:		Skipped	
•	d Switch1 open - Switch2	closed - before command	
Status:		Skipped	
Close command and	d switches open - during	command	
Status:		Skipped	
Close command and	d switches closed - during	g command	
Status:		Skipped	
Open command and	d switches closed		
Status:		Skipped	
Open command and	d switches onen		
Status:	a switches open	Skipped	
		- Спрресс	
TRIP true		Ckinned	
Status:		Skipped	
Initial state clo	need		
Status:	JSEU	Skipped	
Status.		Зкіррец	
TRIP both switches	onen		
Status:	орен	Terminated	
Module Time:		13.5734668	
Begin Sequence: (C:\Users\itlavi	: TRIP both switches open t1\OneDrive - ABB\LabRnD	_Shared\TestStand\Sequence	es\MOD\FMEA.seq)
Closed - Open	- Active - ON - LOG		
Status:	ACTIVE OIN LOG	Done	
Switch 1:		True	
Swtich 2:		False	
Enable Output	s I NG	The state of the s	
Litable Output	3 200		

Done

Open - Open - Active - ON - LOG				
Status:	Done			
Switch 1:	False			
Swtich 2:	False			
Disable Outputs LOG				
Status:	Done			
Open - Closed - Active - ON - LOG	Done			

Closed - Open - Active - ON - LOG		
Status:	Done	
Switch 1:	True	
Swtich 2:	False	

Check Outputs			
Status:	Failed		
Configuration:	TRIP both switches open		
Output_1_SIG:	False		
Output_2_AUX:	True		

End Sequence: TRIP both switches open

End Sequence: MainSequence

End UUT Report