UUT Report

Station ID: IT-W-7303101

Serial Number: NONE

Date: mercoledì 31 maggio 2023

Time: 10:33:02 Operator: administrator

Execution Time: 802.804813 seconds

Number of Results: 717 UUT Result: Passed

Begin Sequence: MainSequence

(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1053.seq)

DUT recap	
Status:	Done
Serial Number:	M086AB1000
Type Designator:	M4M30SEA
FW Version:	P3.0.0.4
PMD-1053	
Status:	Passed
Module Time:	802.7020239

Begin Sequence: PMD-1053

(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1053.seq)

Touch - Go Home	
Status:	Passed
Module Time:	19.0968761

Begin Sequence: Touch_GoHome

(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

Touch - Go To CT Ratio	
Status:	Passed
Module Time:	5.884424

Touch - CT Ratio Decrement	
Status:	Passed
Module Time:	28.1753801

Touch - Go Home	
Status:	Passed
Module Time:	19.249901

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go To Audit Log	
Status:	Passed
Module Time:	9.8270373

Touch - Go Home	
Status:	Passed
Module Time:	19.3269832

Begin Sequence: Touch_GoHome (C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go To Audit Log	
Status:	Passed
Module Time:	9.7857612

Touch - Go Home	
Status:	Passed
Module Time:	19.15068

 $\label{lem:composition} Begin Sequence: Touch_GoHome \\ (C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)$

Pass/Fail - Home Reached	
Status:	Passed

Touch - Go To VT Ratio	
Status:	Passed
Module Time:	5.8718804

Touch - VT Ratio Decrement	
Status:	Passed
Module Time:	20.4643213

Touch - Go Home	
Status:	Passed
Module Time:	19.2425136

Pass/Fail - Home Reached Status: Passed

End Sequence: Touch_GoHome

Touch - Go To Audit Log	
Status:	Passed
Module Time:	9.7720359

Touch - Go Home	
Status:	Passed
Module Time:	19.5143115

Begin Sequence: Touch_GoHome

(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go To Audit Log	
Status:	Passed
Module Time:	9.7967485

Touch Cfg Type Of Network To 2	
Status:	Passed
Module Time:	27.3676047

Begin Sequence: TouchCfgTypeOfNetwork

(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1053.seq)

Touch - Go Home	
Status:	Passed
Module Time:	19.4089368

Begin Sequence: Touch_GoHome

(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

Touch - Go To Type Of Network	
Status:	Passed
Module Time:	5.8692349

Touch - Go Home	
Status:	Skipped

End Sequence: TouchCfgTypeOfNetwork

Check type of Network = 2		
Status:	Passed	
Audit Log Pass/fail - Net Type = 2		
Status:	Skipped	
Touch - Go Home		
Status:	Passed	
Module Time:	19.4982862	

Begin Sequence: Touch_GoHome

(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go To Audit Log	
Status:	Passed
Module Time:	9.7617627

Touch - Go Home	
Status:	Skipped

Check type of Network Pass/Fail	
Status:	Passed

Touch - Go Home	
Status:	Passed
Module Time:	19.2455069

Begin Sequence: Touch_GoHome (C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

Touch - Go To Audit Log	
Status:	Passed
Module Time:	9.7655554

Audit Log Pass/fail - Net Type = 3	
Status:	Passed

Touch - Go Home	
Status:	Passed
Module Time:	19.0835846

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Factory Reset		
Status:	Passed	
Module Time:	30.4480006	

Touch - Go To Audit Log		
Status:	Passed	
Module Time:	9.7781454	

Touch - Go Home		
Status:	Passed	
Module Time:	19.2253597	

Begin Sequence: Touch_GoHome (C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

End Sequence: PMD-1053

End Sequence: MainSequence

End UUT Report