UUT Report

Station ID: IT-W-7303101

Serial Number: NONE

Date: giovedì 30 marzo 2023

Time: 14:30:03 Operator: ITLAVIT1

Execution Time: 00:03:35.075

Number of Results: 417
UUT Result: Passed

Begin Sequence: MainSequence

(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1185.seq)

DUT recap		
Status:	Done	
TestResults/Data:		
Serial Number:	Q032AB102T	
Type Designator:	M4M30SMA	
FW Version:	P3.0.0.3	
PMD-1185		
Status:	Passed	
Module Time:	215.653	

Begin Sequence: PMD-1185

(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1185.seq)

Touch - Go Home	
Status:	Passed
Module Time:	15.3382

Begin Sequence: Touch_GoHome (C:\Users\itlavit1\OneDrive -

ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go To CT Ratio		
Status:	Passed	
Module Time:	5.862	
Touch - CT Ratio Decrement		
Status:	Passed	

Module Time:	26.2694
Touch - Go Home	
Status:	Passed
Module Time:	15.7436

Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go To Audit Log		
Status:	Passed	
Module Time:	9.76715	
Touch - Go Home		
Status:	Passed	
Module Time:	15.5274	

Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go To CT Ratio		
Status:	Passed	
Module Time:	5.89308	
Touch - CT Ratio Increment		
Status:	Passed	
Module Time:	16.2985	
Touch - Go Home		
Status:	Passed	
Module Time:	15.6429	

Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go To Audit Log		
Status:	Passed	
Module Time:	9.75768	
Touch - Go Home		
Status:	Passed	
Module Time:	15.46	

Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go To CT Ratio		
Status:	Passed	
Module Time:	5.88112	
Touch - CT Ratio Increment		
Status:	Passed	
Module Time:	16.3105	
Touch - Go Home		
Status:	Passed	
Module Time:	15.7035	

Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

End Sequence: PMD-1185

End Sequence: MainSequence

End UUT Report