UUT Report

Station ID:	**IT-W-7303101**
Serial Number:	**NONE**
Date:	**mercoledì 29 marzo 2023**
Time:	**12:25:15**
Operator:	**ITLAVIT1**
Execution Time:	**00:07:46.060**
Number of Results:	**718**
UUT Result:	**Passed**

Begin Sequence: MainSequence
(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1053.seq)

DUT recap	
Status:	Done
TestResults/Data:	
Serial Number:	Q032AB102T
Type Designator:	M4M30SMA
FW Version:	P3.0.0.3
PMD-1053	
Status:	Passed
Module Time:	466.484

Begin Sequence: PMD-1053
(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1053.seq)

Touch - Go Home	
Status:	Passed
Module Time:	18.8514

Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go To CT Ratio	
Status:	Passed
Module Time:	5.85109
Touch - CT Ratio Decrement	
Status:	Passed

Module Time:	28.2847
Touch - Go Home	
Status:	Passed
Module Time:	18.8115

**Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive –
ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)**

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go To Audit Log	
Status:	Passed
Module Time:	9.75067
Touch - Go Home	
Status:	Passed
Module Time:	19.0992

**Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive –
ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)**

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go To Audit Log	
Status:	Passed
Module Time:	9.75604
Touch - Go Home	
Status:	Passed
Module Time:	19.2874

**Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive –
ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)**

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go To VT Ratio	
Status:	Passed
Module Time:	5.87367
Touch - VT Ratio Decrement	
Status:	Passed
Module Time:	46.8875
Touch - Go Home	
Status:	Passed
Module Time:	19.0379

**Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive -
ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)**

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go To Audit Log	
Status:	Passed
Module Time:	9.75515
Touch - Go Home	
Status:	Passed
Module Time:	19.1409

**Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive -
ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)**

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go To Audit Log	
Status:	Passed
Module Time:	9.74509
Touch Cfg Type Of Network To 2	
Status:	Passed
Module Time:	26.6022

**Begin Sequence: TouchCfgTypeOfNetwork
(C:\Users\itlavit1\OneDrive -
ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1053.seq)**

Touch - Go Home	
Status:	Passed
Module Time:	18.672

Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive -
ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go To Type Of Network	
Status:	Passed
Module Time:	5.87474
Touch - Go Home	
Status:	Skipped

End Sequence: TouchCfgTypeOfNetwork

Check type of Network = 2	
Status:	Passed
Audit Log Pass/fail - Net Type = 2	
Status:	Skipped
Touch - Go Home	
Status:	Passed
Module Time:	19.075

Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive -
ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go To Audit Log	
Status:	Passed
Module Time:	9.75391
Touch - Go Home	
Status:	Skipped

Check type of Network Pass/Fail	
Status:	Passed

Touch - Go Home	
Status:	Passed
Module Time:	18.8031

**Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive –
ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)**

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go To Audit Log	
Status:	Passed
Module Time:	9.75416

Audit Log Pass/fail - Net Type = 3	
Status:	Passed

Touch - Go Home	
Status:	Passed
Module Time:	18.743

**Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive –
ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)**

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Factory Reset	
Status:	Passed
Module Time:	30.4512
Touch - Go To Audit Log	
Status:	Passed
Module Time:	9.74696
Touch - Go Home	
Status:	Passed
Module Time:	18.8453

**Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive –**

ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

End Sequence: PMD-1053

End Sequence: MainSequence

End UUT Report