UUT Report

Station ID: IT-W-7303101

Serial Number: NONE

Date: martedì 17 gennaio 2023

Time: 15:17:35 Operator: ITLAVIT1

Execution Time: 00:06:13.050

Number of Results: 461
UUT Result: Passed

Begin Sequence: MainSequence

(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1120_Reactive.seq)

| DUT recap | | |
|-------------------|------------|--|
| Status: | Done | |
| TestResults/Data: | | |
| Serial Number: | L103AB101D | |
| Type Designator: | M4M30SEA | |
| FW Version: | P2.6.14.0 | |
| PMD-1120_Reactive | | |
| Status: | Passed | |
| Module Time: | 373.397 | |

Begin Sequence: PMD-1120_Reactive (C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1120_Reactive.seq)

Debug Init
Status: Skipped

| Touch - Go Home | |
|-----------------|--------|
| Status: | Passed |
| Module Time: | 21.408 |

Begin Sequence: Touch_GoHome (C:\Users\itlavit1\OneDrive -

ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached

Status:

Passed

End Sequence: Touch_GoHome

| Touch_GoConfigurationIO | |
|-------------------------|--------|
| Status: | Passed |

| Module Time: | 18.7945 |
|-----------------|---------|
| Touch - Go Home | |
| Status: | Passed |
| Module Time: | 20.3755 |

Begin Sequence: Touch_GoHome (C:\Users\itlavit1\OneDrive ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

| Pass/Fail - Home Reached | |
|--------------------------|--------|
| Status: | Passed |

End Sequence: Touch_GoHome

| Touch - Go Home | |
|-----------------|---------|
| Status: | Passed |
| Module Time: | 20.3292 |

Begin Sequence: Touch_GoHome (C:\Users\itlavit1\OneDrive ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

| Pass/Fail - Home Reached | |
|--------------------------|--------|
| Status: | Passed |

End Sequence: Touch_GoHome

| INPUTS Set Tariff | | |
|-------------------------------------|----------|--|
| Status: | Passed | |
| Module Time: | 0.163799 | |
| Additional Results - Import Test | | |
| Status: | Done | |
| TestResults/Data: | | |
| Import: | 0.76 | |
| Export: | 0 | |
| Import _ Pre Integration: | 0 | |
| Export _ Pre Integration: | 0 | |
| Pass/Fail COMM Import - Import Test | | |
| Status: | Passed | |
| Pass/Fail COMM Export - Import Test | | |
| Status: | Passed | |
| Touch Reactivate | | |
| Status: | Skipped | |
| Touch - Go Home | | |
| Status: | Skipped | |
| Touch ReactiveImport Read | | |
| Status: | Skipped | |

| Pass/Fail HMI - Import Test | |
|-------------------------------------|-----------|
| Status: | Skipped |
| Touch - Go Home | Стирром |
| Status: | Skipped |
| Additional Results - Export Test | |
| Status: | Done |
| TestResults/Data: | |
| Import: | 0.76 |
| Export: | 0.82 |
| Import _ Pre Integration: | 0.76 |
| Export _ Pre Integration: | 0 |
| Pass/Fail COMM Import - Export Test | |
| Status: | Passed |
| Pass/Fail COMM Export - Export Test | |
| Status: | Passed |
| Touch Reactivate | |
| Status: | Skipped |
| Touch - Go Home | |
| Status: | Skipped |
| Touch ReactiveExport Read | |
| Status: | Skipped |
| Pass/Fail HMI - Export Test | |
| Status: | Skipped |
| Touch - Go Home | Clina |
| Status: | Skipped |
| INPUTS Set Tariff Status: | Passed |
| Module Time: | 0.0595077 |
| Additional Results - Import Test | 0.0393077 |
| Status: | Done |
| TestResults/Data: | Done |
| Import: | 0.78 |
| Export: | 0 |
| Import _ Pre Integration: | 0 |
| Export _ Pre Integration: | 0 |
| Pass/Fail COMM Import - Import Test | |
| Status: | Passed |
| Pass/Fail COMM Export - Import Test | |
| Status: | Passed |
| Touch Reactivate | |
| Status: | Skipped |
| Touch - Go Home | |
| Status: | Skipped |
| Touch ReactiveImport Read | |
| Status: | Skipped |
| Pass/Fail HMI - Import Test | |
| Status: | Skipped |
| Status. | экірреа |
| Touch - Go Home | эмэреа |
| | Skipped |

| Additional Results - Export Test | |
|--|---|
| Status: | Done |
| TestResults/Data: | Done |
| · | 0.78 |
| Import: | 0.84 |
| Export: | |
| Import _ Pre Integration: | 0.78 |
| Export _ Pre Integration: | 0 |
| Pass/Fail COMM Import - Export Test | |
| Status: | Passed |
| Pass/Fail COMM Export - Export Test | |
| Status: | Passed |
| Touch Reactivate | |
| Status: | Skipped |
| Touch - Go Home | |
| Status: | Skipped |
| Touch ReactiveExport Read | |
| Status: | Skipped |
| Pass/Fail HMI - Export Test | |
| Status: | <u>Skipped</u> |
| Touch - Go Home | |
| Status: | Skipped |
| INPUTS Set Tariff | |
| Status: | Passed |
| Module Time: | 0.0397719 |
| Additional Results - Import Test | |
| Status: | Done |
| TestResults/Data: | |
| | |
| Import: | 0.75 |
| | 0.75 |
| Export: | 0 |
| Export: Import _ Pre Integration: | 0 |
| Export: Import _ Pre Integration: Export _ Pre Integration: | 0 |
| Export: Import _ Pre Integration: Export _ Pre Integration: Pass/Fail COMM Import - Import Test | 0 0 0 |
| Export: Import _ Pre Integration: Export _ Pre Integration: Pass/Fail COMM Import - Import Test Status: | 0 |
| Export: Import _ Pre Integration: Export _ Pre Integration: Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test | 0 0 0 Passed |
| Export: Import _ Pre Integration: Export _ Pre Integration: Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: | 0 0 0 |
| Export: Import _ Pre Integration: Export _ Pre Integration: Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate | 0 0 0 Passed |
| Export: Import _ Pre Integration: Export _ Pre Integration: Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: | 0 0 0 Passed |
| Export: Import _ Pre Integration: Export _ Pre Integration: Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: Touch - Go Home | 0 0 0 Passed Passed Skipped |
| Export: Import _ Pre Integration: Export _ Pre Integration: Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: Touch - Go Home Status: | 0 0 0 Passed |
| Export: Import _ Pre Integration: Export _ Pre Integration: Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: Touch - Go Home Status: Touch ReactiveImport Read | 0 0 0 Passed Passed Skipped Skipped |
| Export: Import _ Pre Integration: Export _ Pre Integration: Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: Touch - Go Home Status: Touch ReactiveImport Read Status: | 0 0 0 Passed Passed Skipped |
| Export: Import _ Pre Integration: Export _ Pre Integration: Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: Touch - Go Home Status: Touch ReactiveImport Read Status: Pass/Fail HMI - Import Test | 0 0 0 Passed Passed Skipped Skipped |
| Export: Import _ Pre Integration: Export _ Pre Integration: Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: Touch - Go Home Status: Touch ReactiveImport Read Status: Pass/Fail HMI - Import Test Status: | 0 0 0 Passed Passed Skipped Skipped |
| Export: Import _ Pre Integration: Export _ Pre Integration: Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: Touch - Go Home Status: Touch ReactiveImport Read Status: Pass/Fail HMI - Import Test Status: Touch - Go Home | O O O Passed Passed Skipped Skipped Skipped Skipped |
| Export: Import _ Pre Integration: Export _ Pre Integration: Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: Touch - Go Home Status: Touch ReactiveImport Read Status: Pass/Fail HMI - Import Test Status: Touch - Go Home Status: Status: Status: Status: Touch - Go Home | 0 0 0 Passed Passed Skipped Skipped |
| Export: Import _ Pre Integration: Export _ Pre Integration: Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: Touch - Go Home Status: Touch ReactiveImport Read Status: Pass/Fail HMI - Import Test Status: Touch - Go Home Status: Additional Results - Export Test | O O O Passed Passed Skipped Skipped Skipped Skipped |
| Export: Import _ Pre Integration: Export _ Pre Integration: Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: Touch - Go Home Status: Touch ReactiveImport Read Status: Pass/Fail HMI - Import Test Status: Touch - Go Home Status: Status: | O O O Passed Passed Skipped Skipped Skipped Skipped |
| Export: Import _ Pre Integration: Export _ Pre Integration: Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: Touch - Go Home Status: Touch ReactiveImport Read Status: Pass/Fail HMI - Import Test Status: Touch - Go Home | O O O Passed Passed Skipped Skipped Skipped Skipped Skipped Done |
| Export: Import _ Pre Integration: Export _ Pre Integration: Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: Touch - Go Home Status: Touch ReactiveImport Read Status: Pass/Fail HMI - Import Test Status: Touch - Go Home Status: Touch - Go Home Status: Status: Touch - Go Home Status: Touch - Go Home Status: | O O O Passed Passed Skipped Skipped Skipped Skipped |

| Export: | 0.82 |
|---------------------------------------|-----------|
| Import _ Pre Integration: | 0.75 |
| Export _ Pre Integration: | 0 |
| Pass/Fail COMM Import - Export Test | |
| Status: | Passed |
| Pass/Fail COMM Export - Export Test | |
| Status: | Passed |
| Touch Reactivate | |
| Status: | Skipped |
| Touch - Go Home | |
| Status: | Skipped |
| Touch ReactiveExport Read | |
| Status: | Skipped |
| Pass/Fail HMI - Export Test | |
| Status: | Skipped |
| Touch - Go Home | |
| Status: | Skipped |
| INPUTS Set Tariff | |
| Status: | Passed |
| Module Time: | 0.0521585 |
| Additional Results - Import Test | |
| Status: | Done |
| TestResults/Data: | · |
| Import: | 0.8 |
| Export: | 0 |
| Import _ Pre Integration: | 0 |
| Export _ Pre Integration: | 0 |
| Pass/Fail COMM Import - Import Test | |
| Status: | Passed |
| Pass/Fail COMM Export - Import Test | |
| Status: | Passed |
| Touch Reactivate | |
| Status: | Skipped |
| Touch - Go Home | |
| Status: | Skipped |
| Touch ReactiveImport Read | |
| Status: | Skipped |
| Pass/Fail HMI - Import Test | |
| Status: | Skipped |
| Touch - Go Home | |
| Status: | Skipped |
| Additional Results - Export Test | |
| Status: | Done |
| TestResults/Data: | |
| Import: | 0.8 |
| Export: | 0.88 |
| Import _ Pre Integration: | 0.8 |
| Export _ Pre Integration: | 0 |
| · · · · · · · · · · · · · · · · · · · | 1 |

| Status: | Passed |
|---|-----------|
| Pass/Fail COMM Export - Export Test | |
| Status: | Passed |
| Touch Reactivate | |
| Status: | Skipped |
| Touch - Go Home | |
| Status: | Skipped |
| Touch ReactiveExport Read | |
| Status: | Skipped |
| Pass/Fail HMI - Export Test | |
| Status: | Skipped |
| Touch - Go Home | |
| Status: | Skipped |
| INPUTS Set Tariff | |
| Status: | Passed |
| Module Time: | 0.0441553 |
| Additional Results - Import Test | |
| Status: | Done |
| TestResults/Data: | |
| Import: | 0.83 |
| Export: | 0 |
| Import _ Pre Integration: | 0 |
| Export _ Pre Integration: | 0 |
| Pass/Fail COMM Import - Import Test | |
| Status: | Passed |
| Pass/Fail COMM Export - Import Test | |
| Status: | Passed |
| Touch Reactivate | , uoou |
| Status: | Skipped |
| Touch - Go Home | - inprod |
| Status: | Skipped |
| Touch ReactiveImport Read | - inprod |
| Status: | Skipped |
| Pass/Fail HMI - Import Test | - inprod |
| Status: | Skipped |
| Touch - Go Home | |
| Status: | Skipped |
| Additional Results - Export Test | - inprod |
| Status: | Done |
| TestResults/Data: | |
| Import: | 0.83 |
| Export: | 0.82 |
| Import _ Pre Integration: | 0.83 |
| Export _ Pre Integration: | 0.83 |
| Pass/Fail COMM Import - Export Test | U |
| Status: | Passed |
| | rasseu |
| Pacc/Fail COMM Export - Export Toot | |
| Pass/Fail COMM Export - Export Test Status: | Passed |

| Status: | Skipped |
|-------------------------------------|------------|
| Touch - Go Home | |
| Status: | Skipped |
| Touch ReactiveExport Read | |
| Status: | Skipped |
| Pass/Fail HMI - Export Test | |
| Status: | Skipped |
| Touch - Go Home | |
| Status: | Skipped |
| INPUTS Set Tariff | |
| Status: | Passed |
| Module Time: | 0.0527749 |
| Additional Results - Import Test | 0.00277.00 |
| Status: | Done |
| TestResults/Data: | 200 |
| Import: | 0.81 |
| Export: | 0.01 |
| Import _ Pre Integration: | 0 |
| Export _ Pre Integration: | 0 |
| Pass/Fail COMM Import - Import Test | U |
| Status: | Passed |
| Pass/Fail COMM Export - Import Test | rasseu |
| Status: | Passed |
| Touch Reactivate | rasseu |
| Status: | Skipped |
| Touch - Go Home | Экіррец |
| Status: | Ckinned |
| | Skipped |
| Touch ReactiveImport Read | Ckinned |
| Status: | Skipped |
| Pass/Fail HMI - Import Test | Claimped |
| Status: | Skipped |
| Touch - Go Home | Climand |
| Status: | Skipped |
| Additional Results - Export Test | Dana |
| Status: | Done |
| TestResults/Data: | |
| Import: | 0.81 |
| Export: | 0.79 |
| Import _ Pre Integration: | 0.81 |
| Export _ Pre Integration: | 0 |
| Pass/Fail COMM Import - Export Test | |
| Status: | Passed |
| Pass/Fail COMM Export - Export Test | |
| Status: | Passed |
| Touch Reactivate | |
| Status: | Skipped |
| Touch - Go Home | |
| Status: | Skipped |
| Touch ReactiveExport Read | |
| 1 | |

| Status: | Skipped | |
|-----------------------------|---------|--|
| Pass/Fail HMI - Export Test | | |
| Status: | Skipped | |
| Touch - Go Home | | |
| Status: | Skipped | |

| Debug Dispose | |
|---------------|---------|
| Status: | Skipped |

End Sequence: PMD-1120_Reactive

End Sequence: MainSequence

End UUT Report