UUT Report

Station ID: IT-W-7303101

Serial Number: NONE

Date: mercoledì 31 maggio 2023

Time: 09:42:37 Operator: administrator

Execution Time: 394.0311832 seconds

Number of Results: 391 UUT Result: Passed

Begin Sequence: MainSequence

(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1029.seq)

| DUT recap | |
|------------------|-------------|
| Status: | Done |
| Serial Number: | M086AB1000 |
| Type Designator: | M4M30SEA |
| FW Version: | P3.0.0.4 |
| PMD-1029 | |
| Status: | Passed |
| Module Time: | 392.9744395 |

Begin Sequence: PMD-1029

(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1029.seq)

| Touch - Read Timers | |
|---------------------|------------|
| Status: | Passed |
| Module Time: | 66.4996881 |

Begin Sequence: Touch_ReadTimers

(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1029.seq)

| Touch - Go Home | |
|-----------------|------------|
| Status: | Passed |
| Module Time: | 18.9426222 |

Begin Sequence: Touch_GoHome

(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

| Pass/Fail - Home Reached | |
|--------------------------|--------|
| Status: | Passed |

End Sequence: Touch_GoHome

| Touch - Go To Timers | |
|----------------------|-----------|
| Status: | Passed |
| Module Time: | 8.6626006 |

| Touch - Go Home | |
|-----------------|------------|
| Status: | Passed |
| Module Time: | 18.8142231 |

| Pass/Fail - Home Reached | |
|--------------------------|--------|
| Status: | Passed |

End Sequence: Touch_GoHome

End Sequence: Touch_ReadTimers

| Counter Values | |
|-------------------|-------------|
| Status: | Done |
| Counter UP: | 40 |
| Counter DOWN: | 525559 |
| Counter Up HMI: | 40 |
| Counter Down HMI: | 525559 |
| Wait 2 Minutes | |
| Status: | Passed |
| Module Time: | 120.2573531 |

| Touch - Read Timers - After | |
|-----------------------------|------------|
| Status: | Passed |
| Module Time: | 65.7634764 |

Begin Sequence: Touch_ReadTimers (C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1029.seq)

| Touch - Go Home | |
|-----------------|-----------|
| Status: | Passed |
| Module Time: | 18.799984 |

Begin Sequence: Touch_GoHome (C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

| Pass/Fail - Home Reached | |
|--------------------------|--------|
| Status: | Passed |

End Sequence: Touch_GoHome

| Touch - Go To Timers | |
|----------------------|----------|
| Status: | Passed |
| Module Time: | 8.697381 |

| Touch - Go Home | |
|-----------------|------------|
| Status: | Passed |
| Module Time: | 18.6024478 |

Begin Sequence: Touch_GoHome (C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

| Pass/Fail - Home Reached | |
|--------------------------|--------|
| Status: | Passed |

End Sequence: Touch_GoHome

End Sequence: Touch_ReadTimers

| Counter Values after 2 Minutes | | |
|---------------------------------------|--------|--|
| Status: | Done | |
| Counter UP after 2 minute: | 43 | |
| Counter DOWN after 2 minute: | 525556 | |
| Counter UP HMI after 2 minute: | 43 | |
| Counter DOWN HMI after 2 minute: | 525556 | |
| COMM - Check Counters After 2 Minutes | | |
| Status: | Passed | |

| Touch - Start Count Down Start | |
|--------------------------------|------------|
| Status: | Passed |
| Module Time: | 63.1164545 |

Begin Sequence: Touch_SetCountDownStart (C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1029.seq)

| Touch - Go Home | |
|-----------------|------------|
| Status: | Passed |
| Module Time: | 18.6537294 |

Begin Sequence: Touch_GoHome (C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

| Pass/Fail - Home Reached | |
|--------------------------|--------|
| Status: | Passed |

End Sequence: Touch_GoHome

| Touch - Go To Count Down Timer | |
|--------------------------------|------------|
| Status: | Passed |
| Module Time: | 12.9643228 |

End Sequence: Touch_SetCountDownStart

| Touch - Read Timers - Reset | |
|-----------------------------|------------|
| Status: | Passed |
| Module Time: | 65.7255897 |

Begin Sequence: Touch_ReadTimers (C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1029.seq)

| Touch - Go Home | |
|-----------------|------------|
| Status: | Passed |
| Module Time: | 18.8899336 |

| Pass/Fail - Home Reached | |
|--------------------------|--------|
| Status: | Passed |

End Sequence: Touch_GoHome

| Touch - Go To Timers | |
|----------------------|-----------|
| Status: | Passed |
| Module Time: | 8.6495482 |

| Touch - Go Home | |
|-----------------|------------|
| Status: | Passed |
| Module Time: | 18.6697844 |

Begin Sequence: Touch_GoHome (C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

| Pass/Fail - Home Reached | | | |
|--------------------------|--------|--|--|
| Status: | Passed | | |

End Sequence: Touch_GoHome

End Sequence: Touch_ReadTimers

| Counter Values after Reset | | | |
|-------------------------------|--------------|--|--|
| Status: | Done | | |
| Counter UP after Reset: | 0 | | |
| Counter DOWN after Reset: | 239 | | |
| Counter UP after Reset HMI: | 0 | | |
| Counter DOWN after Reset HMI: | 239 | | |
| COMM - UP CNT = 0 | | | |
| Status: | Passed | | |
| COMM - DOWN CNT = 240 | | | |
| Status: | Passed | | |
| Measurement: | 239 | | |
| Limits: | | | |
| Low: | 239 | | |
| High: | 240 | | |
| Comparison Type: | GELE (>= <=) | | |
| HMI - UP CNT = 0 | | | |
| Status: | Passed | | |
| HMI - DOWN CNT = 240 | | | |
| Status: | Passed | | |
| Measurement: | 239 | | |
| Limits: | | | |
| Low: | 238 | | |
| High: | 240 | | |
| Comparison Type: | GELE (>= <=) | | |

End Sequence: PMD-1029

End Sequence: MainSequence