UUT Report

Station ID: IT-W-7303101

Serial Number: NONE

Date: giovedì 12 gennaio 2023

Time: 14:49:06 Operator: ITLAVIT1

Execution Time: 00:05:57.038

Number of Results: 345 UUT Result: Passed

Begin Sequence: MainSequence

(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1803.seq)

DUT recap		
Status:	Done	
TestResults/Data:		
Serial Number:	L103AB101D	
Type Designator:	M4M30SEA	
FW Version:	P2.6.14.0	
PMD-1803		
Status:	Passed	
Module Time:	357.269	

Begin Sequence: PMD-1803

(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1803.seq)

Touch Reset Notifications - Init	
Status:	Passed
Module Time:	47.0083

Begin Sequence: TouchResetNotifications

(C:\Users\itlavit1\OneDrive -

ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1803.seq)

Touch - Go Home	
Status:	Passed
Module Time:	27.0752

Begin Sequence: Touch_GoHome (C:\Users\itlavit1\OneDrive -

ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Reset Notifications	
Status:	Passed
Module Time:	19.7605

End Sequence: TouchResetNotifications

Touch Init WithCheck		
Status:	Passed	
Module Time:	45.6958	
Pass/Fail Touch_IsWorking		
Status:	Passed	
Touch Init WithCheck		
Status:	Passed	
Module Time:	45.6149	
Pass/Fail Touch_IsWorking		
Status:	Passed	

Check Warnings Increment	
Status:	Passed

Touch - Go Home - Read Warnings		
Status:	Skipped	
Touch - Go To Warnings Shortcut - Read Warnings		
Status:	Passed	
Module Time:	5.37664	
Touch - Go Home - Read Warnings		
Status:	Skipped	
Touch Reset Notifications		
Status:	Passed	
Module Time:	46.7908	

Begin Sequence: TouchResetNotifications (C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1803.seq)

Touch - Go Home	
Status:	Passed
Module Time:	26.9437

Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	

Status:	Passed	
---------	--------	--

End Sequence: Touch_GoHome

Touch - Reset Notifications	
Status:	Passed
Module Time:	19.7188

End Sequence: TouchResetNotifications

Touch - Go Home - No Warnings	
Status:	Passed
Module Time:	26.9412

Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go To Warnings - No Warnings		
Status:	Passed	
Module Time:	7.79468	
Touch - Go Home - No Warnings		
Status:	Passed	
Module Time:	26.9574	

Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Check Warnings Num = 1	
Status:	Passed

End Sequence: PMD-1803

End Sequence: MainSequence

End UUT Report