### **UUT Report**

**Station ID: IT-W-7303101** 

Serial Number: NONE

Date: mercoledì 18 gennaio 2023

Time: 09:57:51 Operator: ITLAVIT1

**Execution Time:** 00:12:46.001

Number of Results: 754 UUT Result: Passed

**Begin Sequence: MainSequence** 

(C:\Users\itlavit1\OneDrive - ABB\LabRnD\_Shared\TestStand\Sequences\M4M\PMD-1053.seq)

DUT recap		
Status:	Done	
TestResults/Data:		
Serial Number:	L103AB101D	
Type Designator:	M4M30SEA	
FW Version:	P2.6.14.0	
PMD-1053		
Status:	Passed	
Module Time:	765.248	

**Begin Sequence: PMD-1053** 

(C:\Users\itlavit1\OneDrive - ABB\LabRnD\_Shared\TestStand\Sequences\M4M\PMD-1053.seq)

Touch - Go Home		
Status:	Passed	
Module Time:	22.9542	

Begin Sequence: Touch\_GoHome (C:\Users\itlavit1\OneDrive -

ABB\LabRnD\_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

**End Sequence: Touch\_GoHome** 

Touch - Go To CT Ratio		
Status:	Passed	
Module Time:	5.91216	
Touch - Go Home		
Status:	Passed	

Module Time: 23.0877
----------------------

Pass/Fail - Home Reached	
Status:	Passed

#### **End Sequence: Touch\_GoHome**

Touch - Go To CT Ratio		
Status:	Passed	
Module Time:	5.89322	
Touch - CT Ratio Decrement		
Status:	Passed	
Module Time:	27.8359	
Touch - Go Home		
Status:	Passed	
Module Time:	22.6172	

# Begin Sequence: Touch\_GoHome (C:\Users\itlavit1\OneDrive ABB\LabRnD\_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

#### **End Sequence: Touch\_GoHome**

Touch - Go To Audit Log		
Status:	Passed	
Module Time:	9.76677	
Touch - Go Home		
Status:	Passed	
Module Time:	22.796	

# Begin Sequence: Touch\_GoHome (C:\Users\itlavit1\OneDrive ABB\LabRnD\_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached		
Status:	Passed	

**End Sequence: Touch\_GoHome** 

Touch - Go To Audit Log		
Status:	Passed	
Module Time:	9.78821	
Touch - Go Home		
Status:	Passed	
Module Time:	23.0421	

Pass/Fail - Home Reached	
Status:	Passed

**End Sequence: Touch\_GoHome** 

Touch - Go To VT Ratio	
Status:	Passed
Module Time:	5.88631
Touch - VT Ratio Decrement	
Status:	Passed
Module Time:	36.3026
Touch - Go Home	
Status:	Passed
Module Time:	22.5212

Begin Sequence: Touch\_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD\_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

**End Sequence: Touch\_GoHome** 

Touch - Go To Audit Log	
Status:	Passed
Module Time:	9.79276
Touch - Go Home	
Status:	Passed
Module Time:	22.616

Begin Sequence: Touch\_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD\_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached		
Status:	Passed	

**End Sequence: Touch\_GoHome** 

Touch - Go To Audit Log	
Status:	Passed
Module Time:	9.77953
Touch Cfg Type Of Network To 2	
Status:	Passed
Module Time:	30.7453

Begin Sequence: TouchCfgTypeOfNetwork
(C:\Users\itlavit1\OneDrive ABB\LabRnD\_Shared\TestStand\Sequences\M4M\PMD-1053.seq)

Touch - Go Home	
Status:	Passed
Module Time:	22.8234

Begin Sequence: Touch\_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD\_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

**End Sequence: Touch\_GoHome** 

Touch - Go To Type Of Network	
Status:	Passed
Module Time:	5.87888
Touch - Go Home	
Status:	Skipped

**End Sequence: TouchCfgTypeOfNetwork** 

Check type of Network = 2		
Status:	Passed	
Audit Log Pass/fail - Net Type = 2		
Status:	Skipped	
Touch - Go Home		
Status:	Passed	
Module Time:	23.1346	

Pass/Fail - Home Reached	
Status:	Passed

#### **End Sequence: Touch\_GoHome**

Touch - Go To Audit Log	
Status:	Passed
Module Time:	9.75177
Touch - Go Home	
Status:	Skipped

Check type of Network Pass/Fail	
Status:	Passed

Touch - Go Home	
Status:	Passed
Module Time:	22.8437

Begin Sequence: Touch\_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD\_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

### **End Sequence: Touch\_GoHome**

Touch - Go To Audit Log	
Status:	Passed
Module Time:	9.79751

Audit Log Pass/fail - Net Type = 3		
Status:	Passed	

Touch - Go Home	
Status:	Passed
Module Time:	22.7417

Begin Sequence: Touch\_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD\_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	

Status:	Passed
---------	--------

**End Sequence: Touch\_GoHome** 

Touch - Factory Reset	
Status:	Passed
Module Time:	85.6006
Touch - Go To Audit Log	
Status:	Passed
Module Time:	9.80139
Touch - Go Home	
Status:	Passed
Module Time:	22.7733

Pass/Fail - Home Reached	
Status:	Passed

**End Sequence: Touch\_GoHome** 

**End Sequence: PMD-1053** 

**End Sequence: MainSequence** 

### **End UUT Report**