UUT Report

Station ID: IT-W-7303101

Serial Number: NONE

Date: martedì 21 marzo 2023

Time: 16:08:10 Operator: ITLAVIT1

Execution Time: 00:05:13.090

Number of Results: 349
UUT Result: Passed

Begin Sequence: MainSequence

(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1803.seq)

| DUT recap | |
|-------------------|------------|
| Status: | Done |
| TestResults/Data: | |
| Serial Number: | M086AB1000 |
| Type Designator: | M4M30SEA |
| FW Version: | P3.0.0.3 |
| PMD-1803 | |
| Status: | Passed |
| Module Time: | 313.805 |
| | |

Begin Sequence: PMD-1803

(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1803.seq)

| Touch Reset Notifications - Init | |
|----------------------------------|---------|
| Status: | Passed |
| Module Time: | 38.8748 |

Begin Sequence: TouchResetNotifications

(C:\Users\itlavit1\OneDrive -

ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1803.seq)

| Touch - Go Home | |
|-----------------|---------|
| Status: | Passed |
| Module Time: | 19.0608 |

Begin Sequence: Touch_GoHome (C:\Users\itlavit1\OneDrive -

ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

| Pass/Fail - Home Reached | | |
|--------------------------|--------|--|
| Status: | Passed | |

End Sequence: Touch_GoHome

| Touch - Reset Notifications | |
|-----------------------------|---------|
| Status: | Passed |
| Module Time: | 19.6617 |

End Sequence: TouchResetNotifications

| Touch Init WithCheck | | |
|---------------------------|---------|--|
| Status: | Passed | |
| Module Time: | 39.3642 | |
| Pass/Fail Touch_IsWorking | | |
| Status: | Passed | |
| Touch Init WithCheck | | |
| Status: | Passed | |
| Module Time: | 38.9889 | |
| Pass/Fail Touch_IsWorking | | |
| Status: | Passed | |

| Check Warnings Increment | |
|--------------------------|--------|
| Status: | Passed |

| Touch - Go Home - Read Warnings | | |
|---|---------|--|
| Status: | Skipped | |
| Touch - Go To Warnings Shortcut - Read Warnings | | |
| Status: | Passed | |
| Module Time: | 6.90726 | |
| Touch - Go Home - Read Warnings | | |
| Status: | Skipped | |
| Touch Reset Notifications | | |
| Status: | Passed | |
| Module Time: | 38.7252 | |

Begin Sequence: TouchResetNotifications (C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1803.seq)

| Touch - Go Home | |
|-----------------|---------|
| Status: | Passed |
| Module Time: | 18.8899 |

Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

| Pass/Fail - Home Reached | |
|--------------------------|--|
| | |

| Status: | Passed | |
|---------|--------|--|
|---------|--------|--|

End Sequence: Touch_GoHome

| Touch - Reset Notifications | | |
|-----------------------------|---------|--|
| Status: | Passed | |
| Module Time: | 19.7117 | |

End Sequence: TouchResetNotifications

| Touch - Go Home - No Warnings | |
|-------------------------------|---------|
| Status: | Passed |
| Module Time: | 19.0728 |

Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

| Pass/Fail - Home Reached | |
|--------------------------|--------|
| Status: | Passed |

End Sequence: Touch_GoHome

| Touch - Go To Warnings - No Warnings | | |
|--------------------------------------|--------|--|
| Status: | Passed | |
| Module Time: | 7.808 | |
| Touch - Go Home - No Warnings | | |
| Status: | Passed | |
| Module Time: | 19.041 | |

Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)



End Sequence: Touch_GoHome

| Check Warnings Num = 1 | |
|------------------------|--------|
| Status: | Passed |

End Sequence: PMD-1803

End Sequence: MainSequence

End UUT Report