UUT Report

Station ID:	IT-W-7303101
Serial Number:	NONE
Date:	martedì 21 marzo 2023
Time:	15:53:03
Operator:	ITLAVIT1
Execution Time:	00:03:24.023
Number of Results:	4

Error, Error executing substep 'Run'.
Error 56 occurred at Error 56 occurred at IPSES_Modbus_x64.lvlibp:IP Data Unit.lvclass:Read ADU Packet.vi:5030001

Possible reason(s):

LabVIEW: (Hex 0x38) The network operation exceeded the user-specified or system time limit.

UUT Result:
Complete call chain:
    IPSES_Modbus_x64.lvlibp:IP Data Unit.lvclass:Read ADU Packet.vi:5030001
    IPSES_Modbus_x64.lvlibp:Modbus Master.lvclass:Read Holding Registers.vi:2420001
    IPSES_Modbus_x64.lvlibp:M4M_30.lvlib:M4M_30.lvclass:AuditLog.vi
    IPSES_Modbus_x64.lvlibp:StepModbus.lvlib:RunReadVTRatio.vi
    IPSES_Modbus_x64.lvlibp:StepModbus.lvlib:RunReadVTRatio.vi.ProxyCaller

LabVIEW: (Hex 0x38) The network operation exceeded the user-specified or system time limit. [Error Code: 56, User-defined error code.]

Begin Sequence: MainSequence
(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1182.seq)

DUT recap	
Status:	Done
TestResults/Data:	
Serial Number:	M086AB1000
Type Designator:	M4M30SEA
FW Version:	P3.0.0.3
PMD-1182	
Status:	Error

Error Message: Error executing substep 'Run'.
Error 56 occurred at Error 56 occurred at IPSES_Modbus_x64.lvlibp:IP Data Unit.lvclass:Read ADU Packet.vi:5030001
 	
Possible reason(s):
 	
LabVIEW: (Hex 0x38) The network operation exceeded the user-specified or system time limit.
 	
Complete call chain:
   IPSES_Modbus_x64.lvlibp:IP Data Unit.lvclass:Read ADU Packet.vi:5030001
   IPSES_Modbus_x64.lvlibp:Modbus Master.lvclass:Read Holding Registers.vi:2420001
   IPSES_Modbus_x64.lvlibp:M4M_30.lvlib:M4M_30.lvclass:AuditLog.vi	

IPSES_Modbus_x64.lvlibp:StepModbus.lvlib:RunReadVTRatio.vi
IPSES_Modbus_x64.lvlibp:StepModbus.lvlib:RunReadVTRatio.vi.ProxyCaller

LabVIEW: (Hex 0x38) The network operation exceeded the user-specified or system time limit. [Error Code: 56]

Module Time:	204.139

End Sequence: MainSequence

End UUT Report