UUT Report

Station IT-W-7303101

Serial **NONE**

Number:

lunedì 20 marzo 2023 Date:

11:05:18 Time: **Operator: ITLAVIT1**

Execution 00:00:09.715 Time:

Number

of **15**

Results:

Error, Error executing substep 'Run'.

Error 538183 occurred at Error 538183 occurred at an unidentified location

This error code is undefined. Undefined errors might occur for a number of reasons. For example, no one has provided a description for the code, or you might have wired a number that is not an error code to the error code input.

UUT **Result:** Additionally, undefined error codes might occur because the error relates to a third-party object, such as the operating system or ActiveX. For these third-

party errors, you might be able to obtain a description of the error by searching the Web for the error code (538183) or for its hexadecimal representation (0x00083647).

This error code is undefined. Undefined errors might occur for a number of reasons. For example, no one has provided a description for the code, or you might have wired a number that is not an error code to the error code input.

Additionally, undefined error codes might occur because the error relates to a third-party object, such as the operating system or ActiveX. For these thirdparty errors, you might be able to obtain a description of the error by searching the Web for the error code (538183) or for its hexadecimal representation (0x00083647). [Error Code: 538183, User-defined error code.]

Begin Sequence: MainSequence

(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-2502.seq)

DUT recap	
Status:	Done
TestResults/Data:	
Serial Number:	M086AB1000
Type Designator:	M4M30SEA
FW Version:	P3.0.0.3
PMD-2502	
Status:	Error
Error Message: Error executing substep 'Run'. Error 538183 occurred at Error 538183 occurred at an unidentified location	
This error code is undefined. Undefined errors might occur for a number of reasons. For example, no one has provided a description for the code, or you might have wired a number that is not an error code to the error code input. Additionally, undefined error codes might occur because the error relates to a third-party object, such as the operating system or ActiveX. For these third-party errors, you might be able to obtain a description of the error by searching the Web for the error code (538183) or for its hexadecimal representation (0x00083647).	
This error code is undefined. Undefined errors might occur for a number of reasons. For example, no one has provided a description for the code, or you might have wired a number that is not an error code to the error code input. Additionally, undefined error codes might occur because the error relates to a third-party object, such as the operating system or ActiveX. For these third-party errors, you might be able to obtain a description of the error by searching the Web for the error code (538183) or for its hexadecimal representation (0x00083647). [Error Code: 538183]	
Module Time:	

Begin Sequence: PMD-2502

(C:\Users\itlavit1\OneDrive - ABB\LabRnD Shared\TestStand\Sequences\M4M\PMD-2502.seq)

LOG Set Power As Import

Status:

-- Omicron - Set Power Consumption

Status:

Error Message: Error executing substep 'Run'.

Error 538183 occurred at Error 538183 occurred at an unidentified location

This error code is undefined. Undefined errors might occur for a number of reasons. For example, no one has provided a description for the code, or you might have wired a number that is not an error code to the error code input.

Additionally, undefined error codes might occur because the error relates to a third-party object, such as the operating system or ActiveX. For these third-party errors, you might be able to obtain a description of the error by searching the Web for the error code (538183) or for its hexadecimal representation (0x00083647).

This error code is undefined. Undefined errors might occur for a number of reasons. For example, no one has provided a description for the code, or you might have wired a number that is not an error code to the error code input.

dditionally, undefined error codes might occur because the error relates to a third-party object, such as the operating system or ActiveX. For these third-

party errors, you might be able to obtain a description of the error by searching the Web for the error code (538183) or for its hexadecimal representation (0x00083647). [Error Code: 538183]

Module Time:

Begin Sequence: SetPowerConsumption

(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-2502.seq)

Set Power Consumption Active

|Status:

Error Message: Error executing substep 'Run'.

Error 538183 occurred at Error 538183 occurred at an unidentified location

This error code is undefined. Undefined errors might occur for a number of reasons. For example, no one has provided a description for the code, or you might have wired a number that is not an error code to the error code input.

Additionally, undefined error codes might occur because the error relates to a third-party object, such as the operating system or ActiveX. For these third-

party errors, you might be able to obtain a description of the error by searching the Web for the error code (538183) or for its hexadecimal representation (0x00083647).

This error code is undefined. Undefined errors might occur for a number of reasons. For example, no one has provided a description for the code, or you might have wired a number that is not an error code to the error code input.

Additionally, undefined error codes might occur because the error relates to a third-party object, such as the operating system or ActiveX. For these third-

party errors, you might be able to obtain a description of the error by searching the Web for the error code (538183) or for its hexadecimal representation (0x00083647). [Error Code: 538183]

||Module Time: ||8.8313

End Sequence: SetPowerConsumption

End Sequence: PMD-2502

End Sequence: MainSequence

End UUT Report