UUT Report

Station IT-W-7303101

ID: Serial

Number:

NONE

Date:

lunedì 6 marzo 2023

Time: 14:20:52 **Operator: ITLAVIT1**

Execution 00:00:10.193

Time:

Number

of **13**

Results:

Error, Error executing substep 'Run'.

Error -1073807330 occurred at Property Node (arg 3) in IPSES Modbus x64.lvlibp:Serial Shared Components.lvlib:Configure Serial Port.vi-

>IPSES Modbus x64.lvlibp:Serial Master.lvclass:Initialize Master.vi->IPSES Modbus x64.lvlibp:Modbus Master.lvclass:Initialize.vi-

>IPSES Modbus x64.lvlibp:API Main.lvlib:Create Serial Master.vi-

>IPSES Modbus x64.lvlibp:M4M 30.lvlib:M4M 30.lvclass:Create Master Instance Serial.vi-

UUT

>IPSES Modbus x64.lvlibp:StepModbus.lvlib:RunInitializeCommunication.vi-

Result:

>IPSES Modbus x64.lvlibp:StepModbus.lvlib:RunInitializeCommunication.vi.ProxyCaller

Possible reason(s):

VISA: (Hex 0xBFFF001E) The specified state of the attribute is not valid, or is not supported as defined by the resource.

VISA: (Hex 0xBFFF001E) The specified state of the attribute is not valid, or is not supported as defined by the resource. [Error Code:

-1073807330, User-defined error code.]

End UUT Report