UUT Report

Station ID:	**IT-W-7303101**
Serial Number:	**NONE**
Date:	**mercoledì 29 marzo 2023**
Time:	**10:23:32**
Operator:	**ITLAVIT1**
Execution Time:	**00:07:41.027**
Number of Results:	**392**
UUT Result:	**Passed**

Begin Sequence: MainSequence
(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1029.seq)

DUT recap	
Status:	Done
TestResults/Data:	
Serial Number:	Q032AB102T
Type Designator:	M4M30SMA
FW Version:	P3.0.0.3
PMD-1029	
Status:	Passed
Module Time:	460.279

Begin Sequence: PMD-1029
(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1029.seq)

Touch - Read Timers	
Status:	Passed
Module Time:	64.3043

Begin Sequence: Touch_ReadTimers
(C:\Users\itlavit1\OneDrive -
ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1029.seq)

Touch - Go Home	
Status:	Passed
Module Time:	17.8807

Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive -
ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go To Timers	
Status:	Passed
Module Time:	8.65496
Touch - Go Home	
Status:	Passed
Module Time:	18.2748

Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive –
ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

End Sequence: Touch_ReadTimers

Counter Values	
Status:	Done
TestResults/Data:	
Counter UP:	130
Counter DOWN:	525469
Counter Up HMI:	131
Counter Down HMI:	525468
Wait 2 Minutes	
Status:	Passed
Module Time:	120.253

Touch - Read Timers - After	
Status:	Passed
Module Time:	64.5432

Begin Sequence: Touch_ReadTimers
(C:\Users\itlavit1\OneDrive –
ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1029.seq)

Touch - Go Home	
Status:	Passed
Module Time:	18.2287

**Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive -
ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)**

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go To Timers	
Status:	Passed
Module Time:	8.61529
Touch - Go Home	
Status:	Passed
Module Time:	18.3495

**Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive -
ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)**

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

End Sequence: Touch_ReadTimers

Counter Values after 2 Minutes	
Status:	Done
TestResults/Data:	
Counter UP after 2 minute:	133
Counter DOWN after 2 minute:	525466
Counter UP HMI after 2 minute:	134
Counter DOWN HMI after 2 minute:	525465
COMM - Check Counters After 2 Minutes	
Status:	Passed

Touch - Start Count Down Start	
Status:	Passed
Module Time:	62.4804

**Begin Sequence: Touch_SetCountDownStart
(C:\Users\itlavit1\OneDrive -
ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1029.seq)**

Touch - Go Home

Status:	Passed
Module Time:	17.9654

Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive –
ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go To Count Down Timer	
Status:	Passed
Module Time:	12.9905

End Sequence: Touch_SetCountDownStart

Touch - Read Timers - Reset	
Status:	Passed
Module Time:	64.4193

Begin Sequence: Touch_ReadTimers
(C:\Users\itlavit1\OneDrive –
ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1029.seq)

Touch - Go Home	
Status:	Passed
Module Time:	18.345

Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive –
ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go To Timers	
Status:	Passed
Module Time:	8.66864
Touch - Go Home	
Status:	Passed
Module Time:	18.2372

Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive -
ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

End Sequence: Touch_ReadTimers

Counter Values after Reset	
Status:	Done
TestResults/Data:	
Counter UP after Reset:	0
Counter DOWN after Reset:	239
Counter UP after Reset HMI:	0
Counter DOWN after Reset HMI:	239
COMM - UP CNT = 0	
Status:	Passed
COMM - DOWN CNT = 240	
Status:	Passed
Numeric:	239
Limits:	
Low:	239
High:	240
Comparison Type:	GELE(>= <=)
HMI - UP CNT = 0	
Status:	Passed
HMI - DOWN CNT = 240	
Status:	Passed
Numeric:	239
Limits:	
Low:	238
High:	240
Comparison Type:	GELE(>= <=)

End Sequence: PMD-1029

End Sequence: MainSequence

End UUT Report