Test Software P/N 4102483

Tested Part Number LA1054096

 $\textbf{Test Software Name} \ \underline{\texttt{Trilogy FSA}} \ (\texttt{PM TEST})$



PHILIPS RESPIRONICS

Software Revision 24.0.0.0

Prepared By P. Pascal

Test Report

Step	Description	Units	Limits	Results	Pass Fai
141	0040.0700 SD Locked Card Inserted: SD Detected (7) [30m 2	N/A	EQ YES	YES	√
142	0040.0710 SD Locked Card Inserted: SD Recognized (7) [30m	N/A	EQ YES	YES	√
143	0040.0720 SD Locked Card Inserted: Write Protected Mode (N/A	EQ YES	YES	√
144	0040.0730 SD Card Removed: SD Detected (4) [30m 34s]	N/A	EQ NO	NO	√
145	0040.0740 SD Card Removed: SD Recognized (4) [30m 34s]	N/A	EQ NO	NO	√
146	0040.0750 SD Card Removed: Write Protected Mode (4) [30m	N/A	EQ YES	YES	√
147	0040.0780 SD Unlocked Card Inserted: Write Mode Enable (3	N/A	Pass	TRUE	√
148	0040.0790 SD: File Write [30m 51s]	N/A	Pass	TRUE	√
149	0040.0800 SD: File Length [30m 52s]	N/A	Pass	TRUE	√
150	0040.0810 SD: File Read [30m 53s]	N/A	Pass	TRUE	√
151	0040.0820 SD: File Erase [30m 54s]	N/A	Pass	TRUE	√
152	0040.0840 Nurse Call OFF (NO: 9999,00KOhm, NC: 0,00Ohm) [N/A	Pass	TRUE	√
153	0040.0850 Nurse Call ON (NO: 0,000hm, NC: 9999,00K0hm) [3]	N/A	Pass	TRUE	√
154	0040.0900 P1 with Auto Null Valve Closed at 29,84cmH20 [3]	cmH20	26,84 to 32,84	29,99	√
155	0040.0910 P1 with Auto Null Valve Opened at 63,69cmH2O [3]	cmH20	-3,00 to 3,00	0,00	√
156	0040.0950 Cooling Fans: Stirring Fan [31m 52s]	N/A	Pass	TRUE	√
157	0040.0960 Cooling Fans: Battery Fan [31m 54s]	N/A	Pass	TRUE	√
158	0040.0970 Cooling Fans: Exhaust Fan [32m 5s]	N/A	Pass	TRUE	√
159	0040.1300 Current Consumption in Sleep Mode (1) [33m 16s]	A	LE 0,20	0,00	√
160	0040.1400 O2 Low Flow @ 20,10PSIG [35m 27s]	SLPM	GE 7	9	√
161	0040.1410 DSP CRC: JTAG ID Code [35m 47s]	N/A	EQ 01F4001D	01F4001D	√
162	0040.1420 DSP CRC: DSP Program CRC [35m 47s]	N/A	EQ FE0F	FEOF	√
163	0050.0010 Check Blower Hours [36m 18s]	Hours	3,2	3,2	√
164	0050.0015 Set Backlight [36m 18s]	N/A	Pass	TRUE	
165	0050.0120 Int.Batt.Cap.@(T=28C,SH=80%,CC=159,CF=0,ME=2)	ક	15 to 85	65,00	
166	0050.0121 Det.Bat.Cap.@(T=25C,SH=73%,CC=322,CF=0,ME=2) [3	%	15 to 85	77,00	√
167	0050.0130 Motor Temperature [36m 18s]	C Deg	15 to 82	40	√
168	0050.0200 Significant Event Log (101 entries): [38m 50s]	N/A	Pass	TRUE	√
169	0050.0210 Engineering Debug Log (111 entries): [41m 41s]	N/A	Pass	TRUE	√
170	0050.0140 Battery Ship Mode (0, Success, 1) [42m 21s]	N/A	Pass	TRUE	1
171	0050.0500 HW Power Fail: Red LED Flashing and Alarm [42m	N/A	Pass	TRUE	1
172	0050.0510 HW Power Fail: Dev. rebooted, no red LED/Alarm	N/A	Pass	TRUE	
173	0050.0150 Set Default Parameters [44m 0s]	N/A	Pass	TRUE	1
174	0050.0160 Write Charger Limiter Table (Limit=100%) [44m 2	N/A	Pass	TRUE	· /
175	0050.0170 New Porting Block [44m 21s]	ADC Cnts	0 to 100	Pass	1

Test Started On 04/03/24 09:28:47

Serial Number TV113021326

Elapsed Test Time 48m 32s

Status PASS

Page 5 **of** 6