Test Software P/N 4102483

Tested Part Number 1040000

Test Software Name Trilogy FSA (REPAIR TEST)



Software Revision 24.0.0.0

Prepared By P. Pascal

Test Report

Step	Description	Units	Limits	Results	Pass	Fail
36	0021.0570 02 Positive Flow Cal: dP1 at 64,5 (SP 65 @79,9P	ADC Cnts	LE 1872	1742	√	
37	0021.0580 02 Positive Flow Cal: dP1 at 74,0 (SP 75 @79,3P	ADC Cnts	LE 2006	1873	√	
38	0021.0590 02 Positive Flow Cal: dP1 at 84,0 (SP 85 @78,8P	ADC Cnts	LE 2131	2007	√	
39	0021.0600 02 Positive Flow Cal: dP1 at 94,5 (SP 95 @78,1P	ADC Cnts	LE 2256	2132	√	
40	0021.0610 02 Positive Flow Cal: dP1 at 104,0 (SP 105 @77,	ADC Cnts	LE 2374	2257	✓	
41	0021.0620 02 Positive Flow Cal: dP1 at 114,5 (SP 115 @76,	ADC Cnts	LE 2481	2375	✓	
42	0021.0630 02 Positive Flow Cal: dP1 at 125,2 (SP 125 @76,	ADC Cnts	LE 2573	2482	√	
43	0021.0640 02 Positive Flow Cal: dP1 at 134,7 (SP 135 @75,	ADC Cnts	LE 2651	2574	√	
44	0021.0650 02 Positive Flow Cal: dP1 at 142,8 (SP 145 @74,	ADC Cnts	LE 2931	2652	√	
45	0021.0660 02 Positive Flow Cal: dP1 at 173,6 (SP 175 @72,	ADC Cnts	LE 3059	2932	√	
46	0021.0670 02 Positive Flow Cal: dP1 at 189,2 (SP 190 @70,	ADC Cnts	LE 3999	3060	✓	
47	0021.0880 02 Sensor Cal (RANGE_FAILURE): 4 mV at ambient	N/A	Pass	FALSE		×
48	0021.0930 Write OBM Sensors Cal Table [17m 56s]	N/A	Pass	FALSE		×

Test Started On 08/12/24 11:23:00

Elapsed Test Time 17m 56s

Serial Number TV01606240A

Page 2 **of** 2