Test Software P/N 4102483

Software Revision 24.0.0.0

Tested Part Number LA1054096

 $\textbf{Test Software Name} \ \underline{\texttt{Trilogy FSA}} \ (\texttt{PM TEST})$

Prepared By P. Pascal



Test Report

Step	Description	Units	Limits	Results	Pass Fa
141	0040.0700 SD Locked Card Inserted: SD Detected (7) [47m 5	N/A	EQ YES	YES	√
142	0040.0710 SD Locked Card Inserted: SD Recognized (7) [47m	N/A	EQ YES	YES	✓
143	0040.0720 SD Locked Card Inserted: Write Protected Mode (N/A	EQ YES	YES	√
144	0040.0730 SD Card Removed: SD Detected (4) [47m 59s]	N/A	EQ NO	NO	✓
145	0040.0740 SD Card Removed: SD Recognized (4) [47m 59s]	N/A	EQ NO	NO	√
146	0040.0750 SD Card Removed: Write Protected Mode (4) [47m	N/A	EQ YES	YES	√
147	0040.0780 SD Unlocked Card Inserted: Write Mode Enable (3	N/A	Pass	TRUE	✓
148	0040.0790 SD: File Write [48m 18s]	N/A	Pass	TRUE	✓
149	0040.0800 SD: File Length [48m 19s]	N/A	Pass	TRUE	√
150	0040.0810 SD: File Read [48m 20s]	N/A	Pass	TRUE	✓
151	0040.0820 SD: File Erase [48m 21s]	N/A	Pass	TRUE	✓
152	0040.0840 Nurse Call OFF (NO: 9999,00KOhm, NC: 0,000hm) [N/A	Pass	TRUE	√
153	0040.0850 Nurse Call ON (NO: 0,000hm, NC: 9999,00KOhm) [4	N/A	Pass	TRUE	√
154	0040.0900 P1 with Auto Null Valve Closed at 30,03cmH2O [4	cmH20	27,03 to 33,03	29,98	√
155	0040.0910 P1 with Auto Null Valve Opened at 61,36cmH2O [4	cmH20	-3,00 to 3,00	0,05	
156	0040.0950 Cooling Fans: Stirring Fan [49m 8s]	N/A	Pass	TRUE	
157	0040.0960 Cooling Fans: Battery Fan [49m 10s]	N/A	Pass	TRUE	│
158	0040.0970 Cooling Fans: Exhaust Fan [49m 18s]	N/A	Pass	TRUE	│
159	0040.1300 Current Consumption in Sleep Mode (1) [50m 15s]	A	LE 0,20	0,00	│
160	0040.1400 O2 Low Flow @ 20,20PSIG [53m 0s]	SLPM	GE 7	9	│
161	0040.1410 DSP CRC: JTAG ID Code [53m 19s]	N/A	EQ 01F4001D	01F4001D	│
162	0040.1420 DSP CRC: DSP Program CRC [53m 19s]	N/A	EQ FE0F	FEOF	│
163	0050.0010 Check Blower Hours [53m 41s]	Hours	19399,7	19399,7	│
164	0050.0015 Set Backlight [53m 41s]	N/A	Pass	TRUE	→
165	0050.0120 Int.Batt.Cap.@(T=29C,SH=86%,CC=3,CF=0,ME=1) [53m	ક	15 to 85	69,00	→
166	0050.0121 Det.Bat.Cap.@(T=29C,SH=81%,CC=40,CF=0,ME=1) [53	%	15 to 85	71,00	│
167	0050.0130 Motor Temperature [53m 41s]	C Deg	15 to 82	42	→
168	0050.0200 Significant Event Log (75 entries): [56m 8s]	N/A	Pass	TRUE	│
169	0050.0210 Engineering Debug Log (82 entries): [57m 35s]	N/A	Pass	TRUE	→
170	0050.0140 Battery Ship Mode (0, Success, 1) [58m 18s]	N/A	Pass	TRUE	→
171	0050.0500 HW Power Fail: Red LED Flashing and Alarm [58m	N/A	Pass	TRUE	→
172	0050.0510 HW Power Fail: Dev. rebooted, no red LED/Alarm	N/A	Pass	TRUE	-
173	0050.0150 Set Default Parameters [1 hr 0m 4s]	N/A	Pass	TRUE	
174	0050.0160 Write Charger Limiter Table (Limit=100%) [1 hr	N/A	Pass	TRUE	→
175	0050.0170 New Porting Block [1 hr 0m 28s]	ADC Cnts	0 to 100	Pass	1

Test Started On 03/22/24 12:57:35

Serial Number TV116062358 Elapsed Test Time 1 hr 4m 36s

Status PASS

Page 5 **of** 6