Test Software P/N 4102483

Tested Part Number LA1054096

Test Software Name Trilogy FSA (PM TEST)



Software Revision 24.0.0.0 Prepare

Prepared By P. Pascal

## Test Report

Step	Description	Units	Limits	Results	Pass	Fail
141	0040.0700 SD Locked Card Inserted: SD Detected (7) [29m 5	N/A	EQ YES	YES	<b>√</b>	
142	0040.0710 SD Locked Card Inserted: SD Recognized (7) [29m	N/A	EQ YES	YES	<b>√</b>	
143	0040.0720 SD Locked Card Inserted: Write Protected Mode (	N/A	EQ YES	YES	<b>√</b>	
144	0040.0730 SD Card Removed: SD Detected (4) [30m 1s]	N/A	EQ NO	NO	<b>✓</b>	
145	0040.0740 SD Card Removed: SD Recognized (4) [30m 1s]	N/A	EQ NO	NO	<b>√</b>	
146	0040.0750 SD Card Removed: Write Protected Mode (4) [30m	N/A	EQ YES	YES	✓	
147	0040.0780 SD Unlocked Card Inserted: Write Mode Enable (3	N/A	Pass	TRUE	✓	
148	0040.0790 SD: File Write [30m 18s]	N/A	Pass	TRUE	✓	
149	0040.0800 SD: File Length [30m 19s]	N/A	Pass	TRUE	✓	
150	0040.0810 SD: File Read [30m 20s]	N/A	Pass	TRUE	✓	
151	0040.0820 SD: File Erase [30m 21s]	N/A	Pass	TRUE	✓	
152	0040.0840 Nurse Call OFF (NO: 9999,00KOhm, NC: 0,000hm) [	N/A	Pass	TRUE	✓	
153	0040.0850 Nurse Call ON (NO: 0,000hm, NC: 9999,00KOhm) [3	N/A	Pass	TRUE	<b>√</b>	
154	0040.0900 P1 with Auto Null Valve Closed at 29,40cmH20 [3	cmH20	26,40 to 32,40	29,96	<b>√</b>	
155	0040.0910 P1 with Auto Null Valve Opened at 63,03cmH20 [3	cmH2O	-3,00 to 3,00	0,02	<b>√</b>	
156	0040.0950 Cooling Fans: Stirring Fan [31m 15s]	N/A	Pass	TRUE	<b>√</b>	
157	0040.0960 Cooling Fans: Battery Fan [31m 17s]	N/A	Pass	TRUE	✓	
158	0040.0970 Cooling Fans: Exhaust Fan [31m 26s]	N/A	Pass	TRUE	✓	
159	0040.1300 Current Consumption in Sleep Mode (1) [32m 33s]	A	LE 0,20	0,00	✓	
160	0040.1400 O2 Low Flow @ 20,20PSIG [39m 52s]	SLPM	GE 7	7	✓	
161	0040.1410 DSP CRC: JTAG ID Code [40m 31s]	N/A	EQ 01F4001D	01F4001D	✓	
162	0040.1420 DSP CRC: DSP Program CRC [40m 31s]	N/A	EQ FE0F	FEOF	✓	
163	0050.0010 Check Blower Hours [40m 50s]	Hours	9268,3	9268,3	✓	
164	0050.0015 Set Backlight [40m 50s]	N/A	Pass	TRUE	✓	
165	0050.0120 Int.Batt.Cap.@(T=27C,SH=95%,CC=2,CF=0,ME=1) [40	ક	15 to 85	30,00	✓	
166	0050.0121 Det.Bat.Cap.@(T=27C,SH=99%,CC=0,CF=0,ME=1) [40m	%	15 to 85	81,00	<b>✓</b>	
167	0050.0130 Motor Temperature [40m 50s]	C Deg	15 to 82	36	✓	
168	0050.0200 Significant Event Log (147 entries): [42m 36s]	N/A	Pass	TRUE	<b>✓</b>	
169	0050.0210 Engineering Debug Log (108 entries): [44m 32s]	N/A	Pass	TRUE	✓	
170	0050.0140 Battery Ship Mode (0, Success, 1) [45m 20s]	N/A	Pass	TRUE	<b>√</b>	
171	0050.0500 HW Power Fail: Red LED Flashing and Alarm [46m	N/A	Pass	TRUE	<b>√</b>	
172	0050.0510 HW Power Fail: Dev. rebooted, no red LED/Alarm	N/A	Pass	TRUE	✓	
173	0050.0150 Set Default Parameters [47m 12s]	N/A	Pass	TRUE	<b>√</b>	
174	0050.0160 Write Charger Limiter Table (Limit=100%) [47m 3	N/A	Pass	TRUE	<b>√</b>	
175	0050.0170 New Porting Block [48m 47s]	ADC Cnts	0 to 100	Pass	<b>√</b>	

**Test Started On** 04/23/24 12:13:00

Serial Number TV119042619 Elapsed Test Time 52m 43s

Status PASS

**Page** 5 **of** 6