



OCT Show Roles

Each OCT show must have a single Show Boss and one or more Spotters.

Show Boss - The Show Boss is the person responsible for running the show and the safety of the audience, crew, and effect.



- The Show Boss cannot be inebriated or otherwise impaired during a show.
- The Show Boss must know where all propane cutoffs are and what they do.
- The Show Boss must understand the operation of the OCT Controller
- The Show Boss must know where the fire extinguishers are, how and _when_ to use them.
- The Show Boss must understand how to use Ableton Live, the Launchpad Pro and the external mic to control OCT.
- The Show Boss may, at their sole discretion, allow people into the exclusion zone to use the manual buttons to fire OCT.
- The Show Boss must ready OCT for a show and put it to bed afterwards.
- The Show Boss is the only person to hold the OCT Controller key.



Spotter - The Spotter is responsible for maintaining awareness of the audience and surroundings of OCT during a show and communicating important information to the Show Boss.

- The Spotter cannot be inebriated or otherwise impaired during a show.
- The Spotter may come in and out of the exclusion zone, but should primarily remain outside the zone to maintain situational awareness.
- The Spotter must know where the main gas cutoff is and how to operate it.
- The Spotter must know where the main OCT Controller power switch and kill switch is and how to operate them.
- The Spotter must know where the fire extinguishers are, how and _when_ to operate them.
- The Spotter will take direction from the Show Boss unless they see a dangerous situation and must act to reduce or eliminate that danger.
- The Spotter may bring people to the edge of the exclusion zone and alert the Show Boss that they would like to fire OCT.
- The Spotter is encouraged to take video (within standard Flipside video guidelines.)



OCT from Front of House (FOH)







HP VAPOR SOURCE
(1/4" & 3/8" Hose/Pipe)


SINGLE CUTOFF
SUPPLY LINE
(1" Pipe)


MANIFOLD &
ACCUMULATORS
(3/4" Pipe)


VENTS & PILOTS
(3/8" Hose & 1/2" Pipe,
1/2" Solenoid Valves)




















OPP CLOCK




BIG BOOM




CROSS PLUS




CLOCK




CNT UP



DBL CLOCK



LEFT RIGHT



UPSIE DOWN



