KONTRAK	UNIT	SPK WORKSHOP	JAM KELUAR	JAM MASUK	JAM KERJA	RETASE	JAM BROKEN	JAM DONE	WAKTU MAINTENANCE	KETERANGAN
	DT-315	92804;92803;92802	06:33:00	10:35:00	04:02:00	1	13.28.01	On Process		KEPALA ACCU BERMASALAH (BERULANG), WIPER BERMASALAH LAMPU BELAKANG KIRI KANAN MATI
	DT-316	92818	06:55:00	13:39:00	06:44:00	2	14.42.48	On Process	On Process	CENTER BOLT BELAKANG KIRI PATAH (KERUSAKAN BERULANG SUDAH DIATAS 3 KALI PERBAIKAN)
	DT-329	92758	07:00:00	15:30:00	08:30:00	2	06.53.28	On Process	On Process	LAMPU UTAMA KIRI DAN KANAN MATI
	DT-365	92855;92778	06:57:00	15:44:00	08:47:00	2	08.53.03	On Process	On Process	PATAH BAUT RODA TROMOL NO 6
	DT-379	92814	06:40:00	13:36:00	06:56:00	2	14.22.13	On Process	On Process	U BOLT DEPAN KIRI PATAH
MINING BDM	DT-382	92842;92840	06:54:00	14:47:00	07:53:00	2	16.28.23	On Process		LAMPU UTAMA KANAN MATI; KLAKSON MATI
	DT-389	SPK Belum Input	11:22:00	16:08:00	04:46:00	2	SPK Belum Input	SPK Belum Input	SPK Belum Input	BOCOR BAN NO. 3 (LAODING POINT NAKULA)
	DT-386	92850;92849	06:21:00	15:34:00	09:13:00	3	18.29.13	On Process	On Process	CEK KANPAS BENG GENERAL; STEL REM GENERAL; ADD OUI HUB; KEBCORAN ANGIN DI BELAKANG KABIN;

	Summary
Jml Stage On Process	7
Jml SPK Belum Input	1
Jml SPK Terbuat	12
AVG. Jam Keluar	7
AVG. Jam Masuk	14
AVG. Jam Kerja	6.5
Jml Retase	16
Jml Unit	8

KONTRAK	UNIT	SPK WORKSHOP	JAM KELUAR	JAM MASUK	JAM KERJA	RETASE	JAM BROKEN	JAM DONE	WAKTU MAINTENANCE	KETERANGAN
	DT-318	SPK Belum Input	07:00:00	12:27:00	05:27:00	1	SPK Belum Input	SPK Belum Input	SPK Belum Input	REM BERMASALAH
	DT-331	92836	06:59:00	15:58:00	08:59:00	1	16.19.58	On Process	On Process	GANTI VLEG NO. 5; GANTI BAN NO. 6
	DT-342	92801	06:59:00	11:15:00	04:16:00	1	11.49.53	On Process	On Process	BAUT U BOLT F1 RH LONGGAR, CEK BAUT U BOLT F1 F2, TEKOR ANGIN, CEK INTARDER
	DT-349	92800;92799	06:38:00	10:50:00	04:12:00	1	11.45.29	On Process	On Process	TABUNG ANGIN BERMASALAH (TEKOR ANGIN), REPAIR SPAKBOARD, GANTI KARET STOPPER,
	DT-370	92795	06:48:00	11:10:00	04:22:00	1	11.35.50	On Process	On Process	RAPIKAN SPRING NO. 3 ; DUDUKAN SPRING BELAKANG KIRI KANAN RETAK
	DT-357	92789;92790	06:39:00	10:37:00	03:58:00	1	11.00.55	On Process	On Process	1
RENTAL BDM	DT-339	92810	06:23:00	13:41:00	07:18:00	2	13.58.18	On Process	On Process	PATAH SRING NO 3 BELAKANG KIRI, KLAKSON MATI, TAMBAH AIR RADIATOR, CEK KANPAS KEN NO 2, DAN 3, STEL REM GENERAL
	DT-346	92813	06:58:00	13:37:00	06:39:00	2	14.16.55	On Process	On Process	REPAIR MUFFLER, LOW POWER (KERUSAKAN BERULANG)
	DT-360	92815;92808;92807	06:33:00	13:42:00	07:09:00	2	13.54.49	On Process	On Process	MELEDAK BAN NO 7, PATAH BAUT RODA TROMOL NO 6
	DT-348	92756	07:03:00	16:21:00	09:18:00	3	06.44.11	07.45.08	01.00.57	BOCOR BAN NO 4
	DT-355	92820	06:18:00	15:02:00	08:44:00	3	15.55.23	On Process	On Process	DOBLE BERAT TIDAK BERFUNGSI; KONEKTOR ANGIN BERMASALAH; KEBOCRAN ANGIN DI HOS
	DT-358	92819	06:19:00	15:33:00	09:14:00	3	14.27.31	On Process	On Process	SEAT SPRING BELAKANG KIRI BERMASALAH (STOCKPILE KM 17)
		92823;92822	06:30:00	15:48:00	09:18:00	3	16.00.36	On Process	On Process	STEL REM GENERAL; TAMBHA OLI HUB
		92809	06:35:00	13:48:00	07:13:00	3	13.57.04	On Process	On Process	GANTI BAN NO 3 DAN 4
		92805	06:22:00	17:34:00	11:12:00	3	11.37.16	On Process	On Process	PATAH U BOLT DEPAN BAN NO 1 (JL COR-CORAN BELAKANG)
	DT-375	SPK Belum Input	06:38:00	15:31:00	08:53:00	3	SPK Belum Input	SPK Belum Input	SPK Belum Input	ANTRI/MACET DI PABRIK

	Summary
Jml Stage On Process	13
Jml SPK Belum Input	2
Jml Done	1
Jml SPK Terbuat	19
AVG. Jam Keluar	6
AVG. Jam Masuk	15
AVG. Jam Kerja	8.5
Jml Retase	23
Jml Unit	16

KONTRAK	UNIT	SPK WORKSHOP	JAM KELUAR	JAM MASUK	JAM KERJA	RETASE	JAM BROKEN	JAM DONE	WAKTU MAINTENANCE	KETERANGAN
	DT-507	SPK Belum Input	06:50:00	12:15:00	05:25:00	1	SPK Belum Input	SPK Belum Input	SPK Belum Input	RADIATOR BERMASALAH
	DT-511	92853;92788	07:07:00	16:46:00	09:39:00	2	10.57.12	On Process	On Process	WIPER BERMASALAH, TAMBAH OLI RETARDER
	DT-527	92811	06:47:00	13:45:00	06:58:00	3	14.00.06	17.35.00	03.34.54	LEPAS SPAKBOARD BELAKANG KIRI KANAN
MINING KBM	DT-522	92846	06:59:00	15:01:00	08:02:00	3	16.53.09	On Process	On Process	SERVICE KM 10.000 TAMBAH OLI RETARDER SETEL REM GENERAL CEK KAMPAS REM GENERAL
	DT-524	SPK Belum Input	07:32:00	15:43:00	08:11:00	3	SPK Belum Input	SPK Belum Input	SPK Belum Input	PENGGANTI UNIT 535
	DT-321	SPK Belum Input	13:05:00	16:41:00	03:36:00	1	SPK Belum Input	SPK Belum Input	SPK Belum Input	REPAIR MUFFLER
	DT-322	92798;92797;92796	06:28:00	11:11:00	04:43:00	3	11.42.08	On Process	On Process	LOW POWER,LAS VESEL TALGET OTOMATIS SEBELAH KANAN

	Summary
Jml Stage On Process	3
Jml SPK Belum Input	3
Jml Done	1
Jml SPK Terbuat	7
AVG. Jam Keluar	7
AVG. Jam Masuk	14
AVG. Jam Kerja	6.1
Jml Retase	16
Jml Unit	7