


Name	07xqjk8e.zip	Id.	22754 - Need help
Report Generated on	Sep 30, 2025, 6:11:27 PM	Customer	InstantDFM

Single PCB View - Original



Summary - General - Original

PCB Size	2.008 inch x 1.181 inch	Customer Panel Size	
PCB Thickness	62.992 mil	Max. Aspect Ratio on PTH	unknown
Copper Layers	2	Pressing Stages	unknown
Surface Finish	None	Drill Hole Density	0 Holes/inch ²
Solder Mask	Both	Testable Points	0
Solder Mask Color	Green	Min. SMD/BGA Size	
Legend	Top Only	Via in Pad	No
Legend Color	White	Stacked Vias	
Edge Connector Area	0 inch ²	Castellated	unknown
Peeloff Mask	No	Anomalies	No
Carbon Mask	No		

Summary - Copper Layer Minima - Original

Type	Copper Width	Critical Copper Width	Trace Width	Critical Trace Width	Copper to Copper Clr.	Trace to Trace Clr.	Same Net Clr.	Ring	Copper to Plated Clr.	Copper to NPTH Clr.	Copper to Outline Clr.
	mil	mil	mil	mil	mil	mil	mil	mil	mil	mil	mil
Outer	unknown	unknown	unknown	unknown	unknown	unknown	unknown				>NA

Summary - Sequences - Original

Type	Sequences	Tools	Min. End Dia.	Max. End Dia.	Holes	Routs	Ring on Outer	Ring on Inner	Hole to Copper Clr.
			mil	mil			mil	mil	mil
Total	0								

Name	07xqjk8e.zip	Id.	22754 - Need help
Report Generated on	Sep 30, 2025, 6:11:27 PM	Customer	InstantDFM

Solder Mask - Original

Side	Mask to Mask Clr.	Web	Ring on Cu Defined Pads	Ring on SM Defined Pads	Mask to Copper Clr.	Mask Opening	Fully Covered Via Holes	Partly Covered Via Holes	One Side Covered Vias 	Both Sides Covered Vias 	No Side Covered Vias 
	mil	mil	mil	mil	mil	mil					
Top	unknown	unknown	unknown	unknown	unknown	unknown	No	No			
Bottom	unknown	unknown	unknown	unknown	unknown	unknown	No	No			
Both	unknown	unknown	unknown		unknown	unknown	No	No	No	No	No

Stackup - Original

legend

soldermask

1

2

soldermask

dmakh2_Horns_v0.0-F_Silkscreen_gbr

dmakh2_Horns_v0.0-F_Mask_gbr

1.378 dmakh2_Horns_v0.0-F_Cu_gbr

59.449 FR4

1.378 dmakh2_Horns_v0.0-B_Cu_gbr

dmakh2_Horns_v0.0-B_Mask_gbr

Pressing Stages	
-----------------	--

Summary Minimum Design Characteristics - Locations - Original

Copper Layer Minima & Area - Original

File	Pos.	Copper Width	Critical Copper Width	Trace Width	Critical Trace Width	Copper to Copper Clr.	Same Net Clr.	Copper Area	
		mil	mil	mil	mil	mil	mil	inch ²	%
dmakh2_Horns_v0.0-F_Cu_gbr	1	unknown	unknown	unknown	unknown	unknown	unknown	2.0476	87
dmakh2_Horns_v0.0-B_Cu_gbr	2	unknown	unknown	unknown	unknown	unknown	unknown	2.2477	96

Copper Layer Minima - Copper to Drill Minima - Original

File	Pos.	Ring					Copper to Drill Clr.		Copper to Outline Clr.			
		Overall	Via	Laser Via	Comp.	Mech.	Plated	NPTH	Overall	to Pad	to Trace	to Region
		mil	mil	mil	mil	mil	mil	mil	mil	mil	mil	mil
dmakh2_Horns_v0.0-F_Cu_gbr	1								>NA	>NA	>NA	>NA
dmakh2_Horns_v0.0-B_Cu_gbr	2								>NA	>NA	>NA	>NA

Drill Tools - Original

File	Tool Nr.	Span	Type	Function	Method	Filled Via	Counter	Dia.	Tol. -	Tol. +	Holes in PCB	Routs in PCB	Double Hits	Predrill Hits
								mil	mil	mil				

Drill Tools - Drill vs Copper - Original

File	Tool Nr.	Span	Type	Function	Method	Dia.	Ring on Outer	Ring on Inner	Min. Pad Size	Via in Pad	Plated to Copper Clr. 			
											Overall	to Pad	to Trace	to Region
						mil	mil	mil	mil		mil	mil	mil	mil










Name	07xqjk8e.zip	Id.	22754 - Need help
Report Generated on	Sep 30, 2025, 6:11:27 PM	Customer	InstantDFM

Sequences - Original										
Span	Type	Tools	Min. End Dia.	Max. End Dia.	Holes	Ring on Outer	Ring on Inner	Hole to Copper Clr.	Hole to Outline Clr.	Slot to Outline Clr.
			mil	mil		mil	mil	mil	mil	mil
All	All									

Rout Tools - Original							
File		Tool Nr.	Type	Tool Dia.	End Dia.	Rout Length	Nibble Count
				mil	mil	mil	

Routed Holes - Original							
File		Hole Nr.	Instances	X Size	Y Size	Rout Length	Nibble Count
				mil	mil	mil	

Files - Original

Initial	Renamed	Function	Position	Color	Thickness	
					Base	Finished
					mil	mil
dmakh2_Horns_v0.0-F_Paste.gbr		paste	top			
dmakh2_Horns_v0.0-F_Silkscreen.gbr		silk	top	white	unknown	unknown
dmakh2_Horns_v0.0-F_Mask.gbr		mask	top	green	unknown	unknown
dmakh2_Horns_v0.0-F_Cu.gbr		outer	1		unknown	unknown
dmakh2_Horns_v0.0-B_Cu.gbr		outer	2		unknown	unknown
dmakh2_Horns_v0.0-B_Mask.gbr		mask	bottom	green	unknown	unknown
dmakh2_Horns_v0.0-B_Paste.gbr		empty	none			
dmakh2_Horns_v0.0-B_Silkscreen.gbr		empty	none			
dmakh2_Horns_v0.0-Edge_Cuts.gbr		cad_outline	none			

Input Remarks - Original	
Gerber import: Invalid coincident draw, continuing without cleanup 'dmakh2_Horns_v0.0-B_Cu.gbr'	
Gerber import: Invalid coincident draw, continuing without cleanup 'dmakh2_Horns_v0.0-F_Cu.gbr'	
Gerber import: Invalid contour, continuing with an interpretation. Cannot be cleaned up automatically. Must be cleaned up manually. dmakh2_Horns_v0.0-F_Cu.gbr' (at line 2606)	
DISCREPANCY: Extra bottom layers mismatch between Gerber Job File and current job stackup.	
OMITTED: \$.MaterialStackup[7] not added to layer attributes because corresponding layer could not be found.	
OMITTED: \$.MaterialStackup[8] not added to layer attributes because corresponding layer could not be found.	

Todo's - Original	
Please check the layer structure having no drill layers	

Comments - Original	