Missing-rate and procurement report

DEMONSTRATION EXPORT - NOT SUBMISSION READY - NOT APPROVED FOR ANY REAL TENDER | approvals by: none principals in environment 'test'

SYNTHETIC TEST DATA - FICTIONAL CUSTOMER - NOT A REAL TENDER - NOT A MARKET QUOTE - NOT FOR SUBMISSION

Project ID	PRJ-9201
Project name	PRACTICE TEST - Sample residential building (third-party sample BOQ)
Customer	NONE - practice exercise
Document ID	PRJ-9201-D36
Title	Missing-rate and procurement report
Revision	1
Issue date	2026-10-14
Status	Preliminary (DEMONSTRATION)
Author	test-estimator
Reviewer	not yet reviewed
Estimate version	v1
Estimate fingerprint	400c9f6df7ae5579
Template	T-MISSING-RATES@1.0.0
Confidentiality	CONFIDENTIAL (synthetic test data) - no real customer or supplier data

Summary

48 of 48 BOQ line(s) are unpriced or incomplete in the frozen estimate (never carried as zero).

Unpriced or incomplete BOQ lines

Item	Description	Quantity	Mapping	Pricing
1.1	Excavation in pits for footings	314.04 m3	Unmapped	unpriced
1.2	PCC blinding 50 mm under footings	18.33 m3	Unmapped	unpriced
1.3	Backfill around footings	240.58 m3	Unmapped	unpriced
2.1	Isolated footings	55.4 m3	Unmapped	unpriced
2.2	Columns - Foundation	1.9 m3	Unmapped	unpriced
2.3	Columns - Ground floor	3.3 m3	Unmapped	unpriced
2.4	Columns - First floor	1.56 m3	Unmapped	unpriced
2.5	First-floor beams 200x450	5.21 m3	Unmapped	unpriced
2.6	Roof beams 200x300	2.15 m3	Unmapped	unpriced

Item	Description	Quantity	Mapping	Pricing
2.7	Slab - Ground floor	22.14 m3	Unmapped	unpriced
2.8	Slab - First floor	22.35 m3	Unmapped	unpriced
2.9	Slab - Roof	11.29 m3	Unmapped	unpriced
2.10	RC stairs (flights + landings)	4.13 m3	Unmapped	unpriced
3.1	Footing sides	249.59 m2	Unmapped	unpriced
3.2	Column faces	119.38 m2	Unmapped	unpriced
3.3	Beam sides and soffit	493.69 m2	Unmapped	unpriced
3.4	Slab soffit and edges	884.02 m2	Unmapped	unpriced
4.1	Walls - Ground floor	58.94 m3	Unmapped	unpriced
4.2	Walls - First floor	43.41 m3	Unmapped	unpriced
4.3	Walls - Roof	9.04 m3	Unmapped	unpriced
4.4	Wall plaster area, both faces (gross)	1345.2 m2	Unmapped	unpriced
5.1	Door 900 x 2400 mm	7 nr	Unmapped	unpriced
5.2	Door 800 x 2400 mm	4 nr	Unmapped	unpriced
5.3	Door 802 x 2400 mm	1 nr	Unmapped	unpriced
5.4	Door 6467 x 3140 mm	1 nr	Unmapped	unpriced
5.5	Door 2400 x 2400 mm	1 nr	Unmapped	unpriced
5.6	Door 736 x 2400 mm	1 nr	Unmapped	unpriced
5.7	Door 1300 x 2400 mm	1 nr	Unmapped	unpriced
5.8	Window 800 x 400 mm	3 nr	Unmapped	unpriced
5.9	Window 2460 x 600 mm	2 nr	Unmapped	unpriced
5.10	Window 3000 x 600 mm	2 nr	Unmapped	unpriced
5.11	Window 2600 x 600 mm	2 nr	Unmapped	unpriced
5.12	Window 387 x 3140 mm	2 nr	Unmapped	unpriced
5.13	Window 368 x 3140 mm	2 nr	Unmapped	unpriced
5.14	Window 1500 x 400 mm	2 nr	Unmapped	unpriced
5.15	Window 600 x 2950 mm	2 nr	Unmapped	unpriced
5.16	Window 1206 x 2000 mm	2 nr	Unmapped	unpriced
5.17	Window 1800 x 2000 mm	2 nr	Unmapped	unpriced
5.18	Window 2400 x 2000 mm	2 nr	Unmapped	unpriced
5.19	Window 1160 x 2750 mm	2 nr	Unmapped	unpriced
5.20	Window 1200 x 2000 mm	2 nr	Unmapped	unpriced

Item	Description	Quantity	Mapping	Pricing
5.21	Window 4274 x 2000 mm	1 nr	Unmapped	unpriced
5.22	Window 2500 x 1600 mm	1 nr	Unmapped	unpriced
5.23	Window 4000 x 2000 mm	1 nr	Unmapped	unpriced
5.24	Window 2400 x 2100 mm	1 nr	Unmapped	unpriced
5.25	Window 2400 x 1600 mm	1 nr	Unmapped	unpriced
6.1	Railings and balustrades	43.68 m	Unmapped	unpriced
7.1	Roof and canopy members	48.85 m	Unmapped	unpriced

Procurement needs

No procurement need has been raised, but 48 BOQ line(s) are unpriced (48 unmapped). Procurement needs are detected from MAPPED lines only: map the lines to assemblies/resources first, then run need detection.

ID	Description	Reason	Exposure	Closed
-	none			

Exceptions recorded in the frozen estimate (as at freeze; not necessarily resolved)

Code	Severity	Message
UNPRICED_ITEM	High	BOQ 1.1 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 1.2 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 1.3 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 2.1 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 2.2 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 2.3 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 2.4 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 2.5 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 2.6 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 2.7 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 2.8 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 2.9 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 2.10 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 3.1 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 3.2 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 3.3 has no pricing method/assembly mapping.

Code	Severity	Message
UNPRICED_ITEM	High	BOQ 3.4 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 4.1 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 4.2 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 4.3 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 4.4 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.1 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.2 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.3 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.4 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.5 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.6 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.7 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.8 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.9 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.10 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.11 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.12 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.13 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.14 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.15 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.16 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.17 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.18 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.19 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.20 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.21 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.22 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.23 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.24 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 5.25 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 6.1 has no pricing method/assembly mapping.
UNPRICED_ITEM	High	BOQ 7.1 has no pricing method/assembly mapping.

Code	Severity	Message
POLICY_MISSING	Critical	No commercial policy assigned to the project.

Assumptions, exclusions and limitations

- Quantities are human-measured BOQ quantities; the application does not measure drawings.
- Figures are taken from frozen estimate version v1 (fingerprint 400c9f6df7ae5579).
- SYNTHETIC / DEMONSTRATION data: rates, quotations, productivity norms, customer and responses are fictional test inputs, not market evidence.

Source references

- Frozen estimate version v1 (fingerprint 400c9f6df7ae5579), totals and pricing schedule
- Registers in the application database (see document D33 for received documents, D08 for assumptions, D25 for queries)