

## A32NX

BEFORE START	
COCKPIT PREP	.COMPLETED (BOTH)
GEAR PINS and COVERS	S REMOVED
SIGNS	ON/AUTO
ADIRS	NAV
FUEL QUANTITY	KG.LB
TO DATA	SET
BARO REF	SET (BOTH)
WINDOWS/DOORS	CLOSED (BOTH)
BEACON	ON
THR LEVERS	IDLE
PARKING BRAKE	AS RQRD

AFTER START	
ANTI ICE	AS RQRD
ECAM STATUS	CHECKED
PITCH TRIM	% SET
RUDDER TRIM	

BEFORE TAKEOFF
FLIGHT CONTROLS CHECKED (BOTH)
FLT INST CHECKED (BOTH)
BRIEFINGCONFIRMED
FLAP SETTING CONF (BOTH)
V1, VR, V2/FLX TEMP (BOTH)
ATCSET
ECAM MEMO TO NO BLUE
- AUTO BRK MAX
- SIGNS ON
- CABIN READY
- SPLRS ARM
- FLAPS TO
- TO CONFIRM NORM
TAKEOFF RWY CONFIRMED (BOTH)
CABIN CREW ADVISED
TCAS TA OR TA/RA
ENG MODE SELAS RQRD
PACKS AS RQRD

AFTER TAKEOFF/CLIMB	
LDG GEAR	
FLAPS	
PACKS	ON
BARO REF	

APPROACH	
BRIEFING	CONFIRMED
ECAM STATUS	CHECKED
SEAT BELTS	ON
BARO REF	SET (BOTH)
MINIMUM	SET (BOTH)
ENG MODE SEL	

LANDING	
CABIN CREW ADVIS	ED
A/THRSPEED/C	)FF
AUTOBRAKE AS RQ	RD
ECAM MEMO LDG NO BL	.UE
- LDG GEAR DN	
- SIGNS ON	
- CABIN READY	
- SPLRS ARM	

AFTER LANDING	
FLAPS RETRAC	TED
SPOILERSDISARI	MED
APUST	ART
RADAR	OFF
PREDICTIVE WINDSHEAR SYSTEM	OFF

FLAPS SET

PARKING
APU BLEEDON
ENGINESOFF
SEAT BELTSOFF
EXT LT AS RQRD
FUEL PUMPSOFF
PARK BRK and CHOCKS AS RQRD
Consider HEAVY RAIN

SECURING THE AIRCRAFT	
ADIRSOFF	
OXYGENOFF	
APU BLEEDOFF	
EMER EXIT LTOFF	
SIGNSOFF	
APU AND BATOFF	
Consider COLD WEATHER	