


BAD DESIGN REPORT

Name: Mugilan.R

Registration Number: 23MIS0695



Bad Design 1: Cleaning Machines Blocking Corridor

Description: Cleaning machines are parked in the corridor, reducing walking space and obstructing movement.

Source of Photograph: GPS-enabled own photograph (Captured by me)

Place: VIT University, Vellore

Reasons why the design is bad:

- Obstructs movement.

- Creates safety hazards during emergencies.

- Reduces accessibility.

- Poor space management.

Suggested Improvement:

- Store equipment in a dedicated room.

- Keep corridors free.

- Mark storage areas.



Bad Design 2: Poorly Planned Service Courtyard

Description: Service area contains exposed AC units, debris and poorly utilized space.

Source of Photograph: GPS-enabled own photograph (Captured by me)

Place: VIT University, Vellore

Reasons why the design is bad:

- Untidy layout.

- Poor maintenance.

- Difficult equipment access.

- Poor aesthetics.

Suggested Improvement:

- Organize utilities.

- Improve housekeeping.

- Provide maintenance access.



Bad Design 3: Construction Debris Blocking Walkway

Description: Construction materials and soil block a pedestrian pathway.

Source of Photograph: GPS-enabled own photograph (Captured by me)

Place: VIT University, Vellore

Reasons why the design is bad:

- Trip hazards.

- Restricted movement.

- Dust pollution.

- Unsafe pathway.

Suggested Improvement:

- Remove debris regularly.

- Provide barricades.

- Create a safe alternate walkway.



Bad Design 4: Overflowing Dustbin

Description: Dustbin is overflowing and waste has spilled around it, attracting stray animals.

Source of Photograph: GPS-enabled own photograph (Captured by me)

Place: VIT University, Vellore

Reasons why the design is bad:

- Poor hygiene.

- Bad odor.

- Attracts stray animals.

- Litter spreads around.

Suggested Improvement:

- Increase cleaning frequency.

- Use larger covered bins.

- Promote waste segregation.



Bad Design 5: Non-functional LED Display Board

Description: LED display board above the restaurant appears blank and does not display useful information.

Source of Photograph: GPS-enabled own photograph (Captured by me)

Place: VIT University, Vellore

Reasons why the design is bad:

No information displayed.

Poor communication.

Wasted infrastructure.

Suggested Improvement:

Repair the display.

Show announcements.

Maintain regularly.