


PROPELLANT SAFETY PROTOCOL

Mandatory for every mixing / casting ("cooking") operation.

PROTOCOL STATUS
NO EXCEPTIONS



DOORS STAY FULLY OPEN FOR THE ENTIRE COOK

Continuous airflow, fume dispersal & a clear evacuation route at all times. **Never a sealed room.**

OVERRIDING RULE

EVERY COOK, EVERY TIME – THE TEN RULES

MIXING · CASTING · ENERGETIC MATERIALS

01

FULL PPE IS MANDATORY

Respirator/mask, full face shield, full-sleeve lab coat, chem-resistant gloves, closed-toe shoes. No bare skin on arms or hands.

02

DOORS OPEN – VENTILATION

Entry & exit doors stay fully open the whole operation. Airflow, fume dispersal and the evacuation route must never be blocked.

03

TWO-PERSON RULE

Never work alone with energetic materials. Two trained members minimum – one on the task, one dedicated observer watching work & exit.

04

IGNITION SOURCE CONTROL

No open flames, sparking tools, unshielded electronics, phones or static-generating materials on the propulsion table.

05

FIRE SUPPRESSION ON STANDBY

In-date fire extinguisher within arm's reach before work begins. At least one member present must be briefed on correct use.

06

MINIMUM WORKING QUANTITY

Bring in only what the immediate batch needs. Bulk stock stays in approved storage and is retrieved only as required.

07

SEGREGATED, LABELED STORAGE

Oxidizers, fuels and binders stored separately in approved, labeled containers – away from heat, sunlight & incompatibles.

08

EMERGENCY READINESS

Emergency numbers posted at the entrance. The evacuation route is kept fully clear at all times.

09

HOUSEKEEPING & WASTE

No eating, drinking or food storage in the work area. Clean spills immediately and dispose of waste correctly.


10

TRAINING & PRE-OP SIGN-OFF

Only members who completed propulsion safety training may participate. Pre-operation sign-off required before any cook.

REQUIRED PPE AT ALL TIMES

MUST BE WORN



RESPIRATOR
/ MASK




FULL
FACE SHIELD



FULL-SLEEVE
LAB COAT



CHEM-RESISTANT
GLOVES



CLOSED-TOE
SHOES



STOP

If **any** condition on this sheet cannot be met – **stop work** and notify the propulsion lead immediately.