

Infineon Linux Wi-Fi CYW5551x (Firmware) release notes

About this document

Scope and purpose

Thank you for your interest in Infineon's Linux Wi-Fi Software Release. This document provides an overview of the bug fixes and known issues for the AIROC™ CYW5551x Wi-Fi chips on the current release for Linux.

Intended audience

This document is intended for anyone who uses the Infineon AIROC™ CYW5551X Wi-Fi chips on a Linux host.

Infineon Linux Wi-Fi driver (FMAC) (v2025_0219) release notes



Table of contents

Table of contents

Abou	About this document		
Tabl			
1	Overview	3	
1.1	High-level summary	3	
	Device firmware revision details		
2	Description of firmware changes – CYW5551X	4	

1 Overview

1.1 High-level summary

This document details the bug fixes for CYW5551x on the software release.

This software release includes the following:

- Firmware and Clm blob
 - ifx-Linux-firmware GitHub page

1.2 Device firmware revision details

Table 1 Firmware revision details

Device	Wi-Fi firmware version	
CYW5551X	SDIO	28.10.387.16

Trademarks

 $All\ referenced\ product\ or\ service\ names\ and\ trademarks\ are\ the\ property\ of\ their\ respective\ owners.$

The Bluetooth® word mark and logos are registered trademarks owned by Bluetooth SIG, Inc., and any use of such marks by Infineon is under license.

Edition 2025-02-25 Published by

Infineon Technologies AG 81726 Munich, Germany

© 2025 Infineon Technologies AG. All Rights Reserved.

Do you have a question about this document?

Email:

erratum@infineon.com

Document reference 002-40835 Rev. *A

Important notice

The information given in this document shall in no event be regarded as a guarantee of conditions or characteristics ("Beschaffenheitsgarantie").

With respect to any examples, hints or any typical values stated herein and/or any information regarding the application of the product, Infineon Technologies hereby disclaims any and all warranties and liabilities of any kind, including without limitation warranties of non-infringement of intellectual property rights of any third party.

In addition, any information given in this document is subject to customer's compliance with its obligations stated in this document and any applicable legal requirements, norms and standards concerning customer's products and any use of the product of Infineon Technologies in customer's applications.

The data contained in this document is exclusively intended for technically trained staff. It is the responsibility of customer's technical departments to evaluate the suitability of the product for the intended application and the completeness of the product information given in this document with respect to such application.

Warnings

Due to technical requirements products may contain dangerous substances. For information on the types in question please contact your nearest Infineon Technologies office.

Except as otherwise explicitly approved by Infineon Technologies in a written document signed by authorized representatives of Infineon Technologies, Infineon Technologies' products may not be used in any applications where a failure of the product or any consequences of the use thereof can reasonably be expected to result in personal injury.

2 Description of firmware changes – CYW5551X

Bug fixes

- Fixes the carrier sense issue in JP regulatory.
- Fixes the Tx power update in 6 GHz band.

NVRAM update

Contact the module vendor or local Infineon distribution channel (FAE or local sales representative) to get the latest NVRAM update.

Known issues

- Combo COEX notice UDP low throughput during BLE CIS and Wi-Fi co-ex scenario
- Third party COEX low Zigbee performance noticed Wi-Fi Rx throughput scenario

Trademarks

 $All\ referenced\ product\ or\ service\ names\ and\ trademarks\ are\ the\ property\ of\ their\ respective\ owners.$

The Bluetooth® word mark and logos are registered trademarks owned by Bluetooth SIG, Inc., and any use of such marks by Infineon is under license.

Edition 2025-02-25 Published by

Infineon Technologies AG 81726 Munich, Germany

© 2025 Infineon Technologies AG. All Rights Reserved.

Do you have a question about this document?

Email:

erratum@infineon.com

Document reference 002-40835 Rev. *A

Important notice

The information given in this document shall in no event be regarded as a guarantee of conditions or characteristics ("Beschaffenheitsgarantie").

With respect to any examples, hints or any typical values stated herein and/or any information regarding the application of the product, Infineon Technologies hereby disclaims any and all warranties and liabilities of any kind, including without limitation warranties of non-infringement of intellectual property rights of any third party.

In addition, any information given in this document is subject to customer's compliance with its obligations stated in this document and any applicable legal requirements, norms and standards concerning customer's products and any use of the product of Infineon Technologies in customer's applications.

The data contained in this document is exclusively intended for technically trained staff. It is the responsibility of customer's technical departments to evaluate the suitability of the product for the intended application and the completeness of the product information given in this document with respect to such application.

Warnings

Due to technical requirements products may contain dangerous substances. For information on the types in question please contact your nearest Infineon Technologies office.

Except as otherwise explicitly approved by Infineon Technologies in a written document signed by authorized representatives of Infineon Technologies, Infineon Technologies' products may not be used in any applications where a failure of the product or any consequences of the use thereof can reasonably be expected to result in personal injury.