Emplacement 1	Emplacement 2	Emplacement 3	Code Article	Désignation 1	Désignation 2	N° de lot	Condi.	Unité	Qté empl. 1	Qté empl. 2	Qté empl. 3
Q2 01 A01 01			OR00617465	POINTE T.PLAST.BLC ANN Ø2*30 A4 BT250	(P.150)		0	BOITE			
Q2 01 A01 02			OR00617466	POINTE T.PLAST.BLC ANN Ø2*40 A4 BT250	(P.150)		0	BOITE			
Q2 01 A01 03			OR00617467	POINTE T.PLAST.BLC ANN Ø2,5*50 A4 BT100	(P.150)		0	BOITE			
Q2 01 A01 04			OR00886675	POINTE AITB Ø2,3*40 A4 1KG	(P.141) 740 PTES		0	BOITE			
Q2 01 A01 05			OR00886677	POINTE AITB Ø2,5*50 A4 1KG	(P.141) 500 PTES		0	BOITE			
Q2 01 A01 06			OR00886679	POINTE AITB Ø2,5*60 A4 1KG	(P.141) 400 PTES		0	BOITE			
Q2 01 A02 01			PS3540WEG	VIS HVR 4,0X40 LITEAU ET TASSEAU RLX	EP.14 A 20MM BT/2000		2000	PCES			
Q2 01 A03 02			OR00187540	POINTE TPO Ø2,5*50 AC.BR 5KG	(P.148)		0	BOITE			
Q2 01 A03 03			OR00187549	POINTE TPO Ø2,7*60 AC.BR 5KG	(P.148)		0	BOITE			
Q2 01 B01 01			OR00187555	POINTE TPO Ø3*70 AC.BR 5KG	(P.148)		0	BOITE			
Q2 01 B01 02			OR00187563	POINTE TPO Ø3,5*80 AC.BR 5KG	(P.148)		0	BOITE			
Q2 01 B01 03			OR00187566	POINTE TPO Ø4*90 AC.BR 5KG	(P.148)		0	BOITE			
Q2 01 B02 01			OR00187570	POINTE TPO Ø4,5*100 AC.BR 5KG	(P.148)		0	BOITE			
Q2 01 B02 02			OR00187576	POINTE TPO Ø5*125 AC.BR 5KG	(P.148)		0	BOITE			
Q2 01 B02 03			OR00188150	POINTE TPO Ø5,5*140 AC.BR 5KG	(P.148)		0	BOITE			
Q2 01 B03 01			OR00187556	POINTE TP TORS. Ø3,1*70 AC.BR. 5KG	(P.148)		1	BOITE			
Q2 01 B03 02			OR00187564	POINTE TP TORS. Ø3,5*80 AC.BR. 5KG	(P.148)		1	BOITE			
Q2 01 B03 03			OR00187567	POINTE TP TORS. Ø4*90 AC.BR. 5KG	(P.148)		1	BOITE			
Q2 01 B03 04			OR00188152	POINTE TP TORS. Ø5,5*140 AC.BR. 5KG	(P.148)		1	BOITE			
Q2 01 C01 01			OR00610567	POINTES EN BANDE POUR SABOTS 20° A.G.	4X40 BT/1000 (P.345)		1000	PCES			
Q2 01 C01 02			OR00610568	POINTES EN BANDE POUR SABOTS 20° A.G.	4X50 BT/1000 (P.345)		1000	PCES			
Q2 01 C02 02			OR00610557	POINTES EN BANDE POUR SABOTS 34° 4X40	(P.326) BT/2000		2000	PCES			
Q2 01 C02 04			OR00610558	POINTES EN BANDE POUR SABOTS 34° 4X50	(P.326) BT/2000		2000	PCES			
Q2 01 C03 01			OR00610562	POINTES EN BANDE 20° AG CT 3,1X70MM	(P.330) BT/2000 FIN DE STOCK		2000	PCES			
Q2 01 C03 02			OR03154529	POINTES EN BANDE FH 21° AG 2,8X75MM	(P.344) BT/960		960	PCES			
Q2 01 C03 03			OR03154911	POINTES BANDE 34° SS/GAZ A.B. 2,8X75	BT/4000 (P.345)		4000	PCES			
Q2 01 C03 04			OR00610575	POINTES BANDE 34° SS/GAZ A.B. 3,1X70	(P.331) BT/2200 FIN DE STOCK		2200	PCES			
Q2 01 D01 02			OR03154915	POINTES BANDE 34° SS/GAZ A.B. 3,1X90	BT/3000 (P.345)		3000	PCES			
Q2 01 D01 03			OR03154530	POINTES EN BANDE FH 21° AG 3,1X90MM	(P.344) BT/800		800	PCES			
Q2 01 D01 04			OR00610563	POINTES EN BANDE 20° AG CT 3,1X90MM	(P.330) BT/2000 FIN DE STOCK		2000	PCES			
Q2 01 D02 01			OR00610566	POINTES EN BANDE 20° AG CT 3,8X130MM	(P.330) BT/1500 FIN DE STOCK		1500	PCES			
Q2 01 D02 02			OR03154860	POINTES EN BANDE FH 21° AG 3,8X130MM	(P.344) BT/1250		1250	PCES			
Q2 01 D02 03			OR03154921	POINTES BANDE 34° SS/GAZ A.G. 3,1X90	BT/3000 (P.345)		3000	PCES			

Emplacement 1	Emplacement 2	Emplacement 3	Code Article	Désignation 1	Désignation 2	N° de lot	Condi.	Unité	Qté empl. 1	Qté empl. 2	Qté empl. 3
Q2 01 D02 04			OR00610580	POINTES BANDE 34° SS/GAZ A.G. 3,1X90	(P.331) BT/2200 FIN DE STOCK		2200	PCES			
Q2 01 D03 01			OR00210875	POINTE ANCRAGE 4.0X35 BT1385	(P.112) NFX 10298		0	BOITE			
Q2 01 D03 02			OR00210876	POINTE ANCRAGE 4.0X50 BT980	(P.112) NFX 10300		0	BOITE			
Q2 01 E01 01			OR00886636	POINTES RLX PLATS 16° 2,3X45 AITB L.META	BT/7000		7000	PCES			
Q2 01 E01 02			OR00886637	POINTES RLX PLATS 16° 2,3X50 AITB L.META	BT/7000 (P.349)		7000	PCES			
Q2 01 E01 03			OR00886638	POINTES RLX PLATS 16° 2,3X55 AITB L.META	BT/5600 (P.349)		5600	PCES			
Q2 01 E02 01			SPRS2650AITP65	POINTES RLX PVC 16° 2,5X50 ANN A2 TP	6,5J BT/5250		5250	PCES			
Q2 01 E03 01			OR00610607	POINTES RLX TP PVC 16° 2,8X35	BT/8400 ANNELEE INOX (P.348)		8400	PCES			
Q2 01 E03 02			PACK13	CLOUEUR A SABOT PN34-50MC	+ 4000 PTES 34° PAPIER 4X40 AG		1	UN			