infotekslogistics

Service close-out report

WORK ORDER ITL-SAMPLE-0001
CLIENT TICKET #000000
DATE: MM/DD/YYYY

SAMPLE: illustrative data, not a real job or client

SITE	TECHNICIAN	CHECK-IN	CHECK-OUT
Sample retail store Queens, NY	Tech A (lead) Tech B	09:02	13:47

Scope

Replace two point-of-sale terminals and one network switch in the back office. Test every lane before close-out.

Work performed

#	Task	Status
1	Powered down lanes 2 and 3 with store manager approval	Done
2	Removed old POS terminals; installed and configured replacements	Done
3	Swapped back-office switch; re-patched and labeled 12 ports	Done
4	Test sale and refund on each lane	Passed
5	Packed old units for return; cleaned work area	Done

Parts and serial numbers

Item	Removed (serial)	Installed (serial)
POS terminal, lane 2	SN-OLD-0001	SN-NEW-0001
POS terminal, lane 3	SN-OLD-0002	SN-NEW-0002
24-port switch	SN-OLD-0003	SN-NEW-0003

Photos

Before: lane 2

After: lane 2

Before: switch

After: switch, labeled

Notes

Lane 3 cash drawer cable was frayed and replaced from client stock. No other issues. Store fully operational at 13:40.

Sign-off

Site manager: J. Sample · 13:45

Infotek technician: Tech A · 13:45

Invoice sent with this report the same day. Photos and this report are also uploaded to the client's ticketing portal.

SAMPLE