



DIR-815 Firmware Release Notes

Firmware: FW 1.04.B02

Hardware: A1

Date: 2013/07/30

Note:

None

Problems Resolved:

1. Fixed WLAN 5G LED behavior
2. Fixed Clone MAC address issue in DHCP mode
3. Enhanced performance

Enhancements:

None

Known Issues:

None
