

Main page
Recent changes
Server admin log (Prod)
Server admin log
(RelEng)
Deployments
SRE/Operations Help

Incident status

Cloud VPS & Toolforge Cloud VPS

documentation

Toolforge documentation

Request Cloud VPS project

Server admin log (Cloud VPS)

Tools

What links here Related changes Special pages Permanent link Page information Cite this page

Print/export

Create a book
Download as PDF
Printable version

Page Discussion

Read View source

View history

Search Wikitech

Q

Toolforge webservices are in the final stages of migrating to the toolforge.org domain.

Please help us clean up older documentation referring to tools.wmflabs.org!

Incident documentation/20200224-esams

< Incident documentation

document status: final

Contents [hide]

- 1 Summary
 - 1.1 Impact
 - 1.2 Detection
- 2 Timeline
- 3 Conclusions
 - 3.1 What went well?
 - 3.2 What went poorly?
 - 3.3 Where did we get lucky?
 - 3.4 How many people were involved in the remediation?
- 4 Links to relevant documentation
- 5 Actionables

Summary

A router hardware failure caused widespread issues. While a single hardware failure like that shouldn't cause issues, more hardware failure had preceded this one, lowering our capability to absorb failures.

Impact

All services were affected for all types of users for large portions of Europe and everyone reaching our projects via Amsterdam. That includes parts of Asia and Africa. It is difficult to gauge the exact numbers as it was highly related to the network path from the user to our infrastructure.

Eyeballing the traffic graph do for the interval, we lost about 47M queries over an interval of approx. 20 minutes.

Detection

Humans detected this first. Icinga alerted 1 minute later with pages for cr2-esams arriving to multiple SREs

Timeline

All times in UTC.

- 13:55:55 Pages for cr2-esams arrive at multiple SRE people
- 13:56:37 bast3004 is also down for multiple SRE.
- 14:00:56 XioNoX: cr2-esams: 2020-02-24 13:52:02 UTC Major FPC 0 Major Errors Lkup Error code: 0x40038
- 14:00:04 XioNoX: looks like a linecard failure as well
- 14:03:37 _joe_: esams depooled
- 14:12:05 paravoid: what *works* now?
- 14:14:06 paravoid all cr2-esams interfaces are down
- 14:15:22 paravoid the links to asw2 are et-1/0/0 & et-1/0/1, and show up as up, but are on FPC 1
- 14:15:42 _joe_: now we're in the business of restoring esams
- 14:18:36 bblack: normal volume on vfe-reported GET was 86K/s before the cr2 hit, then it was around 40K just before dns depool, latest sample is ~5K and dropping
- 14:19:41 paravoid: so we have two MX480s both with major FPC errors after a JunOS upgrade
- 14:19:49 paravoid: and a site down
- 14:19:52 XioNoX: paravoid: cr3 didn't get upgraded
- 14:20:23 bblack charting codfw+eqiad+esams aggregate reqs (those involved in the shuffle), we look to be

back at "normal" total reqs as expected, at least roughly https://w.wiki/J65

- 14:28:24 XioNoX: akosiaris: Service Request ID 2020-0224-0258 has been created.
- 14:35:08 marostegui: so, are we fully up? (trying to document stuff)
- 14:35:43 akosiaris: marostegui: as far as I know and as far as users are concerned, yes
- 14:36:00 Outage reported as having ended.
- 14:42:01 paravoid: esams has two MX480s, and both failed today
- 14:42:13 paravoid: eqiad and codfw also have two MX480s for core routers
- 14:48:42 mark: so for RMA
- 14:48:46 mark: we can't swap line cards at esams
- 14:48:49 mark: the PDUs are in the way :)
- 21:40 volansI bblack, XioNoX: just noticed that the CA app email still complains about ns2 IP and in effect I cannot reach ns2
- 22:20 volansl Prefix 91.198.174.0/24: NOT ADVERTISED since 2020-02-24T22:20:13.69323Z, on demand=True
- 22:50 XioNoXl so traffic does internet -> cr3-knams -> cr3-esams -> asw2 -> server
- 22:59 XioNoXI bblack, volans, ns2 is now redirected to eqiad

Conclusions

• esams is a SPOF effectively.

What went well?

- · Automated monitoring detected the incident, outage was understood quickly enough
- · esams was depooled quickly.
- The geo-maps-esams-offline Geographic DNS configuration, created back in January, proved itself well here: we were able to leave esams depooled for some time without overheating eqiad, which had been a problem in the past when esams was depooled during peak traffic times of day. Instead, this map shifts most of eqiad's usual North American traffic westwards to codfw (and some codfw traffic further westwards to ulsfo).

What went poorly?

• We were unlucky enough to have 2 different hardware failures in 2 different routers coincide.

Where did we get lucky?

• It happened during a timeframe were a lot of SREs were awake and fresh.

How many people were involved in the remediation?

• 8 SREs. 2 SRE directors.

Links to relevant documentation

https://wikitech.wikimedia.org/wiki/Network_monitoring#host_(ipv6)_down

 down

 dow

Actionables

 Restricted phabricator tasks T246009

 and T245825
 have been filed for replacing the FPCs on the routers after RMA process was recommendended by the vendor. Tasks are restricted per the usual policy for vendors

Category: Incident documentation

This page was last edited on 27 April 2020, at 14:57.

Text is available under the Creative Commons Attribution-ShareAlike License; additional terms may apply. SeeTerms of Use for details.

Privacy policy About Disclaimers Code of Conduct Developers Statistics Cookie statement Mobile view

Wikitech



