

Main page
Recent changes
Server admin log (Prod)
Server admin log
(RelEng)
Deployments
SRE/Operations Help

Cloud VPS & Toolforge

Cloud VPS documentation

Incident status

Toolforge documentation

Request Cloud VPS project

Server admin log (Cloud VPS)

Tools

What links here Related changes Special pages Permanent link Page information Cite this page

Print/export

Create a book
Download as PDF
Printable version

Page Discussion

Read View source

View history

Search Wikitech

Q

Toolforge webservices are in the final stages of migrating to the toolforge.org domain.

Please help us clean up older documentation referring to tools.wmflabs.org!

Incident documentation/20151127-PartialNetworkOutage

< Incident documentation

Contents [hide]

- 1 Summary
- 2 Timeline
 - 2.1 Timeline of actions
 - 2.2 Timeline of ulsfo routing loop (primary failure)
 - 2.3 Timeline of eqiad cr1/cr2 and row D connectivity failures (secondary failure)
- 3 Conclusions
- 4 Actionables

Summary

A misbehaving Equinix Ashburn customer was flooding the IXP fabric with multicast IPv6 NDP traffic for three and a half hours. At the exact same start time, certain types of packets (multicast/broadcast) sent over one of our cross data center links (between ulsfo and eqiad) started to get amplified (duplicated) up to a few thousand times, saturating the link. It resulted in a flood of (multicast) routing protocol traffic and caused instability on our network, with flapping links and unstable network connectivity.

This, in combination with a routing misconfiguration between eqiad, eqord and ulsfo, caused a cascading partial outage that spanned both the eqiad data center and the network across the US. The primary effect was a ulsfo outage; ulsfo was depooled from DNS 8 minutes into the outage. The secondary effect was issues between the two core routers in eqiad, which may have caused some traffic loss, as well as intermittent connectivity issues with one of the four links to row D, which resulted in unreliable network connectivity for some hosts for about 34 minutes.

This issue mainly impacted users which were routed to our US West Coast caching center for the first 8-18 minutes of the outage, until the traffic was manually rerouted.

Timeline

(all times are UTC)

Timeline of actions

- 09:15 lcinga reports a string of servers going down, most of them in ulsfo, but some in eqiad. lcinga sends pages to the Ops team. Multiple flaps between up and down follow.
- 09:17 Faidon responds first.
- 09:21 Faidon depools ulsfo due to *most* problems being reported there, and reroutes its traffic to eqiad, thereby resolving the problem for the US West Coast and Asian countries in the following minutes.
- 09:22 Mark observes problems on the eqiad core routers cr1-eqiad and cr2-eqiad, including flapping links and even the redundant link between the two routers down in OSPF
- 09:25 Freenode IRC has independent problems of its own and multiple netsplits occur, blocking communication for the Operations team, which in the first 5 minutes isn't evident (this is very meta)
- 09:25 Faidon and Mark investigate independently due to Freenode issues, and focus on the eqiad failures now ulsfo has been depooled. They correlate all connectivity problems for servers in eqiad to row D.
- 09:39 Faidon suspects cr2-eqiad FPC5, as multiple problems correlate to a group of 4 of its ports.
- 09:44 Mark disables two links on FPC5 of the LACP link between cr1-eqiad and cr2-eqiad connectivity between the two router is restored immediately.
- 09:47 Mark disables the link to row D on cr2-eqiad FPC5.
- 09:49 Mark lowers VRRP priority for all VRRP sessions on cr2-eqiad all connectivity problems to servers in

eqiad disappear.

- 09:52 Mark disables all remaining links on cr2-eqiad:xe-5/2/*
- 09:54 All issues are now resolved.
- 09:55 Faidon investigates ongoing connectivity issues to ulsfo (which is drained from all traffic), which seems to be caused by a routing loop
- 10:22 Faidon finds and fixes an inconsistency in the BGP confederation setup in ulsfo

Later in the day, Faidon and Mark concluded that a hardware problem was *not* likely the culprit. After reenabling one of the 4 ports, the link between ulsfo and eqiad, the packet flood returned - this time without user impact due to the depooled state of ulsfo. Faidon isolated the problem to packet amplification by the MPLS link, which was duplicating packets (for free! Black Friday deal?)

Timeline of ulsfo routing loop (primary failure)

- 09:12:59 An Equinix customer starts flooding the Equinix Ashburn IXP fabric with NDPv6 traffic
- 09:12:59 An MPLS link between cr1-ulsfo and cr2-eqiad (xe-5/2/2) starts amplifying traffic
- 09:12:59 cr2-eqiad, which has the affected link to ulsfo as well as the Equinix Ashburn port on FPC 5 (xe-5/3/3) gets flooded with NDPv6/OSPF/PIM multicast traffic
- 09:12:59 cr2-eqiad starts losing BFD/OSPF/OSPFv3 sessions for links on FPC 5: xe-5/2/2 to cr1-ulsfo:xe-0/0/3 (GTT) and xe-5/2/3 to cr2-codfw:xe-5/0/1 (Zayo) due to FPC5 DoS protection dropping packets
- 09:12:59 09:13:00 cr1-ulsfo detects BFD session with cr2-eqiad as down
- 09:13:01 09:15:22 cr1-ulsfo BFD sessions & OSPF for both cr2-eqiad and cr1-eqord flap multiple times
- 09:13-09:55 cr1-ulsfo's IGP & BGP convergence maxes out its CPU
- 09:17:06, 09:17:23 cr1-ulsfo loses BGP peering with PyBal on lvs4001/lvs4002 due to hold timer expired, probably due to the CPU exhaustion
- 09:15:22 09:53:18 intermittent ulsfo LVS traffic loops between cr1-ulsfo and cr1-eqord
- 09:18:35 cr1-ulsfo to pybal BGP connectivity is restored but does not win over in preference
- 09:13:01- 09:53:18 cr1-ulsfo BFD sessions for cr1-eqord flap continue to flap every few seconds, possibly due to the increased CPU
- 09:21 09:31 Faidon depools ulsfo, restoring user-visible ulsfo impact; no visible change to the 10G traffic loop
- 09:52 09:55 Mark disables cr1-ulsfo to cr2-eqiad GTT link
- 09:59 Alex/Faidon detect the routing loop which disappears shortly after
- 10:00 ulsfo-eqiad loop disappears, OSPF/BGP converge across all sites
- 10:20-10:40 Faidon founds ulsfo/eqord/eqiad routing loop cause (BGP confederation misconfiguration) and fixes it; this resets all BGP sessions that took ~20 minutes to converge
- 11:52 Equinix informs customers of an issue with the IXP service (5-33496044285)
- 12:42 NDPv6 flood traffic disappears from the IXP fabric
- 14:31 Equinix informs customers that their engineers have "isolated & stopped the source of unwanted traffic on the DC Metro Internet Exchange" as of 13:40 UTC.

Timeline of eqiad cr1/cr2 and row D connectivity failures (secondary failure)

- 09:12:59 An Equinix IX customer starts flooding the Equinix Ashburn IXP fabric with NDPv6
- 09:12:59 An MPLS link between cr1-ulsfo and cr2-eqiad (xe-5/2/2) starts amplifying traffic
- 09:12:59 cr2-eqiad, which has the affected link to ulsfo as well as the Equinix Ashburn port on FPC 5 (xe-5/3/3) gets flooded with NDPv6/OSPF/PIM multicast traffic
- 09:13:04 cr2-eqiad DoS protection for FPC 5 kicks in, starts dropping traffic for various traffic classes
- 09:15:22 09:53:18 ulsfo incoming LVS traffic loops and amplifies between cr1-ulsfo and cr2-eqiad, contributing to a large traffic surge (10Gbps in small packets) and possibly contributing to FPC 5's issues
- 09:13:04 09:58:00 cr2-eqiad xe-5/2/* interfaces start blackholing partial traffic, including xe-5/2/0 (cr1-eqiad), xe-5/2/1 (asw-d-eqiad), xe-5/2/2 (cr1-ulsfo), xe-5/2/3 (cr2-codfw)
- 09:44 Mark disables xe-5/2/0, restoring connectivity to cr1-eqiad
- 09:47 Mark disables xe-5/2/1, restoring connectivity issues to row D servers
- 09:52 Mark disables xe-5/2/2 & xe-5/2/3

Conclusions

A packet flood by another Equinix customer on the Ashburn Internet Exchange, as well as packet amplification on a (likely technically related) cross data center link caused issues for traffic to the control plane of the router connected to both. This triggered a series of other events in the network, primarily in the form of network-wide

OSPF instability and a routing loop with the ulsfo site due to a misconfiguration in the BGP confederation setup there.

The network is redundant on multiple levels, and this allowed the problem to be routed around. However, explicit Icinga alerting for flapping BFD and OSPF sessions could have sped up the problem investigation somewhat.

MPLS transport links have caused the majority of interconnectivity issues in the past, and are already being phased out in favor of dedicated wavelength paths.

Actionables

- Status: Unresolved Alerts for BFD sessions and OSPF (bug T83992)
- V Done Fix ulsfo confederation inconsistency and audit all other BGP confederation configurations
- Status: Unresolved Investigate why disabling an uplink port did not deprioritize VRRP on cr2-eqiad (bug T119759)
- Done Raise a ticket with GTT to investigate traffic amplification on the MPLS link (GTT TT#931715)

Category: Incident documentation

Wikitech

This page was last edited on 30 November 2015, at 12:59.

Text is available under the Creative Commons Attribution-ShareAlike License; additional terms may apply. SeeTerms of Use for

Privacy policy About

Disclaimers Code of Conduct Developers Statistics Cookie statement Mobile view

(WIKIMEDIA

