

Main page
Recent changes
Server admin log (Prod)
Server admin log
(RelEng)
Deployments
SRE/Operations Help
Incident status

Cloud VPS & Toolforge

Cloud VPS documentation

Toolforge documentation

Request Cloud VPS project

Server admin log (Cloud VPS)

Tools

What links here Related changes Special pages Permanent link Page information Cite this page

Print/export

Create a book
Download as PDF
Printable version

Page Discussion

Read View source

View history

Search Wikitech

Q

Toolforge webservices are in the final stages of migrating to the toolforge.org domain.

Please help us clean up older documentation referring to tools.wmflabs.org!

# Incident documentation/20150413-LabsNFS

< Incident documentation

#### Contents [hide]

- 1 Summary
- 2 Timeline
- 3 Conclusions
- 4 Actionables

#### Summary

Labstore1001 became unresponsive to NFS because its block device subsystem was overloaded. A combination of factors caused a cascade failure resulting in complete resource starvation for NFS.

#### **Timeline**

17:30 Marc noticed NFS is slow during a fairly large copy, thinks the copy might be the cause

17:34 Initial diagnostic on labstore1001 show NFS is starved out of disk bandwidth

17:41 labstore1001 kernel stuck on kworker and bdflush processes, starved for IO 17:50 increase IO priority of NFS process hoping to improve interactive performance

18:00 minor improvements visible, some NFS service restored, but not much

18:17 \_joe\_ joins investigation

18:20 one of the shelves is rebuilding raid6, suspected of being an issue but reducing bandwidth does not visibly help

18:29 stoping NFS and unmounting filesystems to cold start labstore1001

18:33 cold start of labstore1001, go into MD800 BIOS to check diagnostics

18:36 No failures in the hardware reported, proceeding with boot

18:44 NFS back up.

18:53 NFS spotty at best, very high iowait still noticable with disk usage pegged

19:02 bblack joins investigation

19:33 Another cold start to do the bootstrap manually, trying to isolate the problem component

19:38 attempt to let the raid resync proceed, would take 20h at current (overly slow) rate

20:05 mark suggest tuning stripe\_cache\_size to increase rebuild speed. Increases efficiency tenfold.

20:08 noted how raid6 is bound to a single CPU in labstore1001's older kernel, no further improvement in raid6 speed possible

20:12 reduce rebuild speed to leave some IO bandwidth, restart NFS

20:22 NFS returns to reasonable working order, with some intermitent sluggishness

20:47 Most things return to working order, while Coren and Yuvi restore some services that did not survive the outage

21:12 All services back to normal, but iowait remains high

01:34 iowait on labstore1001 returns to normal patterns. Cause unknown as rebuild still in progress.

### Conclusions

There seems to be no single, isolable cause to the outage. Rather, a combination of factors seem to have resulted in the demand on disk bandwidth to exceed the capacity of the system to the point where cascading failure was reached. The kernel stripe\_cache\_size being set to the default (too small) kernel value amplified the drain on resources caused by the raid resync to the point where a buffer flush initiated by the kernel ended up

starving all processes out of disk bandwidth. In addition, the older kernel (from Precise) has a bottleneck on raid6 checksum calculation being single-CPU bound that aggravated matters.

## **Actionables**

- make certain the stripe\_cache\_size setting is puppetized and applied at boot https://phabricator.wikimedia.org/T96045 @
- Formulate plans for getting off of raid6 for labs NFS storage. https://phabricator.wikimedia.org/T96063 &
- Formulate plans for reducing unnecessary NFS I/O by pushing projects to use local storage for heavy i/o traffic. https://phabricator.wikimedia.org/T96065

Category: Incident documentation

This page was last edited on 15 April 2015, at 17:26.

Text is available under the Creative Commons Attribution-ShareAlike License; additional terms may apply. SeeTerms of Use for

Privacy policy About

Disclaimers Code of Conduct Developers Statistics Cookie statement Mobile view

[ Powered By MediaWiki

Wikitech

