Version 1.1 | 2026.06.10 | English

Cong Gear

Manual for 道 Path

Slackline Webbing

Welcome to the Cong Gear Family

Hello Highliner,

Welcome to the fold. By choosing Path, you aren't just buying a piece of gear; you're investing in a product born from a deep obsession with textile engineering and the pursuit of the perfect catch.

We designed Path to be the backbone of your most ambitious projects. It is lean, incredibly strong, and built to handle the unique demands of high-load rigging. Whether you are establishing a new line or pushing your personal limits, we are honored to be part of your journey.

For your safety and better usability,
please carefully read all instructions.
Stay safe, rig smart, and enjoy the walk.
— The Cong Gear Team

Please regularly check for updates and new information on this product temporarily by scaning the QR code at the end of the manual.

1. Technical Specifications

Path is a high-performance HMPE (High Modulus Polyethylene) webbing engineered for maximum strength-to-weight ratio.

Attribute	Specification
Material	100% HMPE (High Modulus Polyethylene)
Width / Thickness	20 mm / 3 mm
Weight	31 g/m ±0.5
Weave Structure	Flat
MBS (Sewn Loop)	40 kN
WLL	12 kN
ISA 41 Class	Type A+
Elongation	Ultra-Low (2.2%@5kN 2.9%@ 10kN)

2. Label Nomenclature



Cong Gear Logo

Name of the webbing

MBS & WLL info

Batch NO./recommended service time

ISA & Manual icons

The reverse of the tag is left blank
to accommodate custom personalization

3. Nomenclature



Webbing: 50m and 100m segment avaliable (Sewn Loop included)
Sewn Loop: For easy connecting segments
Stitching: Using HMPE thread, color and stitch pattern are subject to change alongside ongoing optimization of sewing construction and breaking strength. Nevertheless, every item shipped is produced adopting the latest, most reliable stitching specification.
Label: Product information regarding the webbing (see above), to be affixed inside the sewn loop at one end of each segment.

4. Safety Warning & Liability Disclaimer

1. Inherent Risk & User Responsibility
Slacklining is inherently dangerous and carries a risk of serious injury or death. By using this equipment, you acknowledge these risks and assume full responsibility for any resulting damage or harm.

2. Training & Preparation

Seek Professional Instruction:
These instructions are not exhaustive. Users must obtain specific training to operate this gear safely.

Rescue Readiness:
You must have a rescue plan and the means to execute it. Inert suspension in a harness can be fatal.

Mandatory Briefing:
All users must read and thoroughly understand these instructions before every use.

3. Equipment & Environment

Redundancy:
Never trust your life to a single tool; always utilize a backup system.

Routine Inspections:
Carefully check all equipment for potential failure before and after each use.

Hazard Avoidance:
DO NOT use near electrical hazards, machinery, sharp edges, or abrasive surfaces.

Low Coefficient Of Surface Friction:
Use extreme caution when entering the line, particularly at angles or with wet webbing.The webbing's low-friction characteristics make slips hard to stop and produce dangerous frictional heat.

Surface Protection:
To ensure the longevity and safety of your gear, avoid all contact between the webbing and the ground. Dragging the webbing introduces grit into the weave and creates heat through friction, both of which permanently weaken the fibers. Use a ground tarp or carry the webbing to prevent surface-related damage.

4. Liability
Neither Cong Gear nor its vendors are liable for any direct, indirect, or accidental damages—physical or property-related—arising from the use of this device, in particular any and all losses incurred by performing actions expressly prohibited or strongly discouraged in the product manual (marked as **DO NOT**)

Use at your own risk.

!DO NOT EXCEED THE WORKING LOAD LIMIT!

NOTE: Working load limits (WLL) vary based on your specific configuration and intended application. Always verify that your setup aligns with safety thresholds.

5. Termination Method

Approved termination:
Only the sewn loops are allowed for webbing termination
To maintain system integrity, **DO NOT** install path webbing directly into weblock devices nor use webbing grip devices directly on this webbing. For optimal results, please use a short piece of dynamic webbing that adheres to the ISA Type A minimum strength requirements to connect to the Path webbing then only install the dynamic webbing in the weblock with a anti slippage tail tie-off connect to a solid anchor.

Strict Prohibition:
DO NOT use carabiners to anchor sewn loops—only approved shackles are permitted (Pleast check ISA website for approved gear).
DO NOT tie any knots for fixing the webbing to anchors.

Exercise due caution when installing path webbing with non-20 mm weblocks. Cong Gear shall assume no liability for any damage, injury or adverse consequences arising from improper operation or failure to comply with official manual instructions.

Recommended connection method:

Mandatory Technical Requirements
When selecting a connection method, users must strictly comply with all four conditions below. Failure to meet any of these requirements constitutes improper use, and the user assumes all associated risks.

1. Strength Redundancy
Every individual primary load-bearing connection point and backup connection point must have a Minimum Breaking Strength (MBS) equal to or greater than the webbing's MBS (≥ 40 kN).

2. Bending Radius Limit
Where a webbing loop contacts any rigid connector, the internal bending radius of the loop must be ≥ 8 mm.

3. Inspectability & Redundancy
Inspectability: The connection must allow direct visual or tactile inspection of its integrity, wear, and locking status before every use.
Redundancy: The system must feature an independent backup protection point. If any single connection point fails, the system must prevent a catastrophic fall.

4. Soft Thimble Specification
Using a soft thimble, it must be suitably rated with a recommended minimum width of 20 mm and a minimum thickness of 2.5 mm.

Notice: Cong Gear shall not be held liable for any injury, death, or property damage arising directly or indirectly from the connection method chosen, configured, or implemented by the user.

6. Intended Use

Use only with energy-absorbing components. Always keep slack out of the system to prevent high-impact falls.
Intended strictly for medically fit, trained, and experienced experts or under their direct supervision.
You are responsible for monitoring working loads and ensuring all combined components are compatible and safe.

Use Case Graphic Guidance:
Sewn components must not be cross-loaded; pull only in one direction away from stitching to avoid seam failure.



Backup Loop Rule:
Backup loops may only be used in conjunction with the main loop.

7. Length compatibility chart for highlines

Recommended mainline material depending on highline length				
Length [m]	20 - 30	30 - 40	40 - 200	> 200
Nominal load [kN]	> 2	> 2	> 1	> 1
PA				
PES				
Ultra low-stretch				

8. Webbing Lifespan

The following chart describes the recommended lifetimes (RLT) for webbings of different strengths and materials. These lifetimes are to be interpreted as "days exposed to the elements / days in use" and NOT as the literal age of the webbing (date from manufacture).

Strength Class	Nylon*	Polyester*	HMPE	All Other
Type C	180 Days		Not certified as single webbings	
Type B	360 Days	360 Days		
Type A	720 Days	Optical/Haptic Inspection	No recommendation	
Type A+				

These numbers represent the recommended lifetimes for normal use. Intensive use (festivals, competitions, etc.) or harsh environments (strong UV, high winds, sand, salt water, etc.) can drastically reduce the lifetime of highline webbing. In any case, it is strongly recommended to document the number of days the webbing was used for, to have a good understanding of when to retire the webbing from highline use.

9. Guarantees and Warranties

Cong Gear provides a one-year limited warranty to the original purchaser against defects in materials and workmanship.

This coverage excludes normal wear and tear, modifications, or damage from misuse. Please note that full recalls apply only to products in new and unused condition.

10. Transport, Storage, Care and Lifetime

1. Precautions
Avoid contact with heat sources, abrasive or sharp objects, corrosive substances and solvents.

2. Cleaning & Drying
Use fresh, lukewarm water to wash away abrasive salt and grit. Use a mild, pH-neutral soap. Hand wash or use a delicate machine cycle inside a mesh bag.Never use a dryer or high heat, which can damage the molecular structure. Avoid steer clear of bleach, harsh solvents, and prolonged direct sunlight.If the webbing feels stiff once dry, simply flex it by hand to restore its suppleness.

3. Wear Warning
Moisture, ice, salt, sand, snow, chemicals and other contaminants will hinder normal use and greatly accelerate wear. Exposure to chemicals may result in catastrophic loss of tensile strength. Any webbing with known or suspected chemical contamination must be permanently decommissioned and destroyed to prevent accidental reuse

4. Regular Inspection
Check all components for deformation, corrosion and wear. Examine the full-length fibers of the webbing to ensure no breakage, abrasion or laceration that may reduce its strength and service life. Routinely inspect the overall system to confirm firm connection, correct equipment placement and fully locked connectors.

5. Repair & Modification
Any unauthorized repair or modification of the webbing is forbidden. Relevant work shall only be conducted by the manufacturer or personnel with written official authorization.

6. Service Life
The service life of the webbing varies by application conditions. In extreme cases, it shall be scrapped after one single use. Always monitor the service status and usage frequency.

7. Scrap Regulations
Take the webbing out of service and destroy it permanently if it is overloaded beyond the WLL under any scenario, fails inspection, has potential safety risks, suffers misuse, alteration, damage or exposure to harmful chemicals. Contact the manufacturer for any safety doubts.

8. Transportation & Storage
Store and transport the webbing in a durable bag in neatly flaked or coiled form. Do not place hardware or sharp objects in the same bag to prevent accidental damage.

10. Manufacturer Contact

Cong Gear
Shanghai Balance Sports Development Co., Ltd.
Room 201J, Building 14, No. 655 Fengzhou Road, Jiading District, Shanghai
Website: Under construction
Email: riodinho.x@gmail.com/278297750@qq.com
Phone: +86 177 0127 0356

Report any and all accidents or incidents to the International Slackline Association (ISA) through their Slackline Accident and Incident Report (SAIR) form through the following link:

https://sair.slacklineinternational.org

Cong Gear/Shanghai Balance Sports Development Co., Ltd. is an industry partner of the ISA. You can view more information about this association at their website here:

https://www.slacklineinternational.org

@CONG_GEAR

BEFORE THE OFFICIAL WEBSITE LAUNCH,
PLEASE SCAN THE QR CODE FOR THE LATEST UPDATES.
WE APOLOGIZE FOR ANY INCONVENIENCE CAUSED.