

Work Instruction for Operating Trim Press

Document No. 30-WI-PR-08

Rev. No. & Rev. Date

01/10.08.2019

MASTER COPY

Scope: For Trimming Press of 1000T, 1T, 2T & 3T.

Responsibility: Operator

Method:

- 1. Start the press switch.
- 2. Start lubrication system and confirm it is working.
- 3. After ready signal is on take a trial stroke.
- 4. Load the trimming punch and dies and confirm punch entry.
- 5. During trimming ensure the part is red hot.
- 6. Parts which are not red hot should be kept aside for-re heating
- 7. After unloading of trimming tools clean the machine and surrounding area.
- 8. While switching off the machine use emergency switch.
- 9. Close the Main switch.

PREPARED BY.	APPROVED BY.
Supervisor Production	Head Production