


Wiring Diagram



- To connect the Circuit to your microcontroller, follow the diagram below.
- Make sure your Circuit and microcontroller share a common ground.


UART Mode

TX on your Circuit connects to RX on your microcontroller.



I²C Mode

- SDA on your Circuit connects to SDA on your microcontroller.
- SCL on your Circuit connects to SCL on your microcontroller.



Protoboards or Perfboards should never be used.

