# • Vulnerability description

Matter devices contain a denial-of-service vulnerability that allows an attacker to send malicious Matter messages to the devices, causing a denial-of-service problem.

#### • Affected product information

Name	Firmware Version	Notes
Nanoleaf Light strip	v.3.5.10	Amazon Link

#### CVE-ID

CVE-2023-45955

### Vulnerability type

**Denial of Service** 

#### • Triggering vulnerabilities

The bug is related to the write binding attribute command in the Binding cluster, which is used to establish a persistent relationship between an endpoint and one or more local or remote endpoints. This command accepts a list of parameters in the following two types: List[node-id, endpoint-id, cluster-id] or List[group-id].

Command	Exploit	Observed Device Status
Write Attribute Binding	Write_Attribute_ Binding(0x654321, 1, 8)	Matter Lightstrip <i>crashes</i>
Write Attribute Binding	Write_Attribute_Bind ingd(0)	Matter Lightstrip crashes

Once this malformed command is sent, the Lightstrip crashed. 1) It flickered briefly and became unresponsive, resulting in a timeout exception. 2) The reboot count increased.

## Attack vectors

By sending an exploit Matter message to the device