• Vulnerability description

Matter devices contain a denial-of-service vulnerability that allows an attacker to send malicious Matter messages to the devices, causing a denial-of-service problem.

• Affected product information

Name	Firmware Version	Notes
Nanoleaf Light strip	v.3.5.10	Amazon Link

CVE-ID

CVE-2023-45955

Vulnerability type

Denial of Service

• Triggering vulnerabilities

The bug is related to the write binding attribute command in the Binding cluster, which is used to establish a persistent relationship between an endpoint and one or more local or remote endpoints. This command accepts a list of parameters in the following two types: List[node-id, endpoint-id, cluster-id] or List[group-id].

Command	Exploit	Observed Device Status
Write Binding attribute	Binding(0x654321, 1, 8)	Matter Lightstrip crashes
Write Binding attribute	Binding(1)	Matter Lightstrip crashes

Once this malformed command is sent, the Lightstrip crashed. 1) It flickered briefly and became unresponsive, resulting in a timeout exception. 2) The reboot count increased.

Attack vectors

By sending an exploit Matter message to the device