






NI SC-2345: "SCC1" - Measurement & Automation Explorer
File Edit View Tools Help
Configuration
My System
Data Neighborhood
NI-DAQmx Tasks
MyVoltageTask
Devices and Interfaces
NI SC-2345: "SCC1"
1: NI SCC-AI03: "SCC1
2: NI SCC-AI03: "SCC1
5: NI SCC-TC02: "SCC1
17: NI SCC-AO10: "SC
18: NI SCC-AO10: "SC
21: NI SCC-PWR02: "S
NI PCI-6259 "Dev2"
Network Devices
PXI System (Unidentified)
Scales
Software
IVI Drivers
Remote Systems
Properties
Delete
Show Help
Cabled Device
PCI-6259: "Dev2"
Cabled Device Connector
0
SCC Connector Block ID
SCC1
Power
J21 SCC-PWR02
J18 SCC-AO10
J17 SCC-AO10
AO
J20 None
J19 None
GPCTR
J8 None
J7 None
J6 None
J5 SCC-TC02
J4 None
J3 None
J2 SCC-AI03
J1 SCC-AI03
AI
J16 None
J15 None
J14 None
J13 None
J12 None
J11 None
J10 None
J9 None
DIO
SCC Connector Block Configuration



17: NI SCC-AO10: "SCC1Mod17" - Measurement & Automation Explorer
File Edit View Tools Help
Configuration
Delete
Test Panels...
Device Pinouts
Configure TEDS...
Hide Help
Name
Value
Product Type
SCC-AO10
Device Name
SCC1Mod17
Test Panels : 17: NI SCC-AO10: "SCC1Mod17"
Analog Output
Channel Name
SCC1Mod17/ao0
Max Output Limit
10
Rate (Hz)
1000
Mode
Sinewave Generation
Min Output Limit
-10
Transfer Mechanism
<Default>
Sinewave Amplitude
Frequency (Hz)
1,00000
Running
Stop
Help
Close
Back
NI-DAQmx Device Basics
What do you want to do?
Run the NI-DAQmx Test Panels
Remove the device
View or change device properties
Attributes



Untitled 2 Front Panel *
File Edit View Project Operate Tools Window Help
15pt Application Font
stop
STOP
Untitled 2 Block Diagram *
File Edit View Project Operate Tools Window Help
15pt Application Font
1. Double-click the DAQ Assistant Express VI to configure it. It will launch a wizard that helps you set up your measurement o
Create New Express Task...
NI-DAQ
DAQ Assistant
NATIONAL INSTRUMENTS
Select the measurement type for the task.
A task is a collection of one or more virtual channels with timing, triggering, and other properties.
To have multiple measurement types within a single task, you must first create the task with one measurement type. After you create the task, click the Add Channels button to add a new measurement type to the task.
Acquire Signals
Generate Signals
Analog Output
Voltage
Current
Counter Output
Digital Output
< Back
Next >
Finish
Cancel
stop


Untitled 2 Front Panel *
File Edit View Project Operate Tools Window Help
15pt Application Font
stop
STOP
Untitled 2 Block Diagram *
File Edit View Project Operate Tools Window Help
15pt Application Font
1. Double-click the DAQ Assistant Express VI to configure it. It will launch a wizard that helps you set up your measurement o
Create New Express Task...
NI-DAQ
DAQ Assistant
NATIONAL INSTRUMENTS
Select the physical channel(s) to add to the task.
If you have previously configured global virtual channels of the same measurement type as the task, click the Virtual tab to add or copy global virtual channels to the task. When you copy the global virtual channel to the task, it becomes a local virtual channel. When you add a global virtual channel to the task, the task uses the actual global virtual channel, and any changes to that global virtual channel are reflected in the task.
If you have TEDS configured, click the TEDS tab to add TEDS channels to the task.
For hardware that supports multiple channels in a task, you can select multiple channels to add to a task at the same time.
Physical
Supported Physical Channels
Dev2 (PCI-6259)
SCC1Mod17 (SCC-AO10)
ao0
SCC1Mod18 (SCC-AO10)
<Ctrl> or <Shift> click to select multiple channels.
< Back
Next >
Finish
Cancel
stop


L11_1.vi Front Panel
File Edit View Project Operate Tools Window Help
15pt Application Font
frecventa
10
amplitudine
1
Waveform Graph
Plot 0
Amplitude
Time
Time
Amplitude
Cursors:
X
Y
stop
STOP
Controls
Search
View
Express
User Controls
Select a Control...
Tools
L11_1.vi Block Diagram
File Edit View Project Operate Tools Window Help
15pt Application Font
1. Double-click the DAQ Assistant Express VI to configure it. It will launch a wizard that helps you set up your measurement or gen
2. Once you have completed the wizard, display or output your data in one of the following ways:
Analog Input measurement: Right-click the data terminal of the DAQ Assistant Express VI and select Create Graph Indicator to display your data in a graph.
Analog Output measurement: Wire a data source to the data terminal of the DAQ Assistant Express VI. To generate data, use the Simulate Signal Express VI from the Functions Input Palette.
Counter Input or Digital Input measurement: Right-click the data terminal of the DAQ Assistant Express VI and select Create Numeric Indicator.
Counter Output or Digital Output measurement: Right-click the data terminal of the DAQ Assistant Express VI and select Create Control. From the resulting control, you can output any data.
3. Add signal analysis to your VI by using the Express VIs on the Functions Signal Analysis palette.
4. Add logging to your VI by using the Express File Write Express VI on the Functions Output palette.
frecventa
amplitudine
Sine Waveform.vi
DAQ Assistant
data
Waveform Graph
stop


L11_2.vi
File Edit View Project Operate Tools Window Help
frecventa
10
amplitudine
1
Waveform Graph
Plot 0
Amplitude
Time
Time
Amplitude
Cursors:
X
Y
stop
STOP
Controls
Search
View
Express
User Controls
Select a Control...
Tools
L11_2.vi Block Diagram
File Edit View Project Operate Tools Window Help
1. Double-click the DAQ Assistant Express VI to configure it. It will launch a wizard that helps you set up your measurement or gen
2. Once you have completed the wizard, display or output your data in one of the following ways:
Analog Input measurement: Right-click the data terminal of the DAQ Assistant Express VI and select Create Graph Indicator to display your data in a graph.
Analog Output measurement: Wire a data source to the data terminal of the DAQ Assistant Express VI. To generate data, use the Simulate Signal Express VI from the Functions Input Palette.
Counter Input or Digital Input measurement: Right-click the data terminal of the DAQ Assistant Express VI and select Create Numeric Indicator.
Counter Output or Digital Output measurement: Right-click the data terminal of the DAQ Assistant Express VI and select Create Control. From the resulting control, you can output any data.
3. Add signal analysis to your VI by using the Express VIs on the Functions Signal Analysis palette.
4. Add logging to your VI by using the Express File Write Express VI on the Functions Output palette.
frecventa
amplitudine
Square Waveform.vi
DAQ Assistant
data
Waveform Graph
stop


Untitled 3 Front Panel *
File Edit View Project Operate Tools Window Help
15pt Application Font
stop
STOP
Untitled 3 Block Diagram *
File Edit View Project Operate Tools Window Help
15pt Application Font
1. Double-click the DAQ Assistant Express VI to configure it. It will launch a wizard that helps you set up your measurement o
Create New Express Task...
NI-DAQ
DAQ Assistant
NATIONAL INSTRUMENTS
Select the physical channel(s) to add to the task.
If you have previously configured global virtual channels of the same measurement type as the task, click the Virtual tab to add or copy global virtual channels to the task. When you copy the global virtual channel to the task, it becomes a local virtual channel. When you add a global virtual channel to the task, the task uses the actual global virtual channel, and any changes to that global virtual channel are reflected in the task.
If you have TEDS configured, click the TEDS tab to add TEDS channels to the task.
For hardware that supports multiple channels in a task, you can select multiple channels to add to a task at the same time.
Physical
Supported Physical Channels
Dev2 (PCI-6259)
SCC1Mod17 (SCC-AO10)
ao0
SCC1Mod18 (SCC-AO10)
ao0
<Ctrl> or <Shift> click to select multiple channels.
< Back
Next >
Finish
Cancel
stop
STOP


L11_3.vi
File Edit View Project Operate Tools Window Help
frecventa
10
amplitudine
1
frecventa 2
10
amplitudine 2
1
Waveform Graph
Plot 0
Amplitude
Time
Time
Amplitude
Cursors:
X
Y
stop
STOP
Controls
Search
View
Express
User Controls
Select a Control...
Tools
L11_3.vi Block Diagram
File Edit View Project Operate Tools Window Help
1. Double-click the DAQ Assistant Express VI to configure it. It will launch a wizard that helps you set up your measurement o
2. Once you have completed the wizard, display or output your data in one of the following ways:
Analog Input measurement: Right-click the data terminal of the DAQ Assistant Express VI and select Create Graph Indicator to display your data in a graph.
Analog Output measurement: Wire a data source to the data terminal of the DAQ Assistant Express VI. To generate data, use the Simulate Signal Express VI from the Functions Input Palette.
Counter Input or Digital Input measurement: Right-click the data terminal of the DAQ Assistant Express VI and select Create Numeric Indicator.
Counter Output or Digital Output measurement: Right-click the data terminal of the DAQ Assistant Express VI and select Create Control. From the resulting control, you can output any data.
3. Add signal analysis to your VI by using the Express VIs on the Functions Signal Analysis palette.
4. Add logging to your VI by using the Express File Write Express VI on the Functions Output palette.
frecventa
amplitudine
frecventa 2
amplitudine 2
Sine Waveform.vi
Square Waveform.vi
Merge Signals
DAQ Assistant
data
Waveform Graph
stop