1. Table of Contents (This Page)
   Created on Mon Dec 30 09:57:32 2013
2. component
3. solder
4. outline
5. plated-drill
6. componentmask
7. soldermask
8. topsilk
9. bottomsilk
10. toppaste
11. bottompaste
12. topassembly
13. bottomassembly
14. fab



top, scale = 1:1.000
ckt-signal-1x.pcb



bottom (mirrored), scale = 1:1.000
ckt-signal-1x.pcb



outline, scale = 1:1.000
ckt-signal-1x.pcb



plated-drill, scale = 1:1.000
ckt-signal-1x.pcb

topmask, scale = 1:1.000
ckt-signal-1x.pcb

bottommask (mirrored), scale = 1:1.000
ckt-signal-1x.pcb



topsilk, scale = 1:1.000
ckt-signal-1x.pcb



bottomsilk (mirrored), scale = 1:1.000
ckt-signal-1x.pcb



toppaste, scale = 1:1.000
ckt-signal-1x.pcb



bottompaste (mirrored), scale = 1:1.000
ckt-signal-1x.pcb



topassembly, scale = 1:1.000
ckt-signal-1x.pcb



bottomassembly (mirrored), scale = 1:1.000
ckt-signal-1x.pcb

There are 2 different drill sizes used in this layout, 10 holes total

Symbol	Diam. (Inch)	Count	Plated?
×	0.020	4	YES
+	0.038	6	YES

Title: (unknown) – Fabrication Drawing
Author: Michael Petersen
Date: Mon 30 Dec 2013 04:57:32 PM GMT UTC



Board outline is the centerline of this path

fab, scale = 1:1.000
ckt-signal-1x.pcb