




- 1. Table of Contents (This Page) Created on Mon Apr 15 21:33:52 2013
- 2. component
- 3. solder
- 4. plated-drill
- 5. componentmask
- 6. soldermask
- 7. topsilk
- 8. bottomsilk
- 9. toppaste
- 10. topassembly
- 11. bottomassembly
- 12. fab


























There are 8 different drill sizes used in this layout, 285 holes total Sumbol Diam. (Inch) Count Plated?

Title: (unknown) - Fabrication Drawing Ruthor: Michael Petersen Date: Tue 16 Apr 2013 03:93:53 AM GMT UTC Maximum Dimensions: 5259.000000 mils wide, 1700.000000 mils hi # # # # # # # # # # # # # # # # # # #	YES	* * * * * * * * * * * * * * * * * * *	0.038 0.045 0.048 0.128 0.129	· - > + X >
Date: Tue 16 Apr 2013 03:33:53 AM GMT UTC	YES		0.128	- ф
niver van Nichael Petersen Author: Michael Petersen	YES		0.048) þ e-
	YES		860.0	• 1
	YES	12	0.035	×
	YES	48	0.030	+
	YES	26	0.020	>
	Plated?		Diam. (Inch) Lount	Symbol

d outline is the centerline of this 8.000000 mil rectangle - 0,0 to 5250.000000,1700.000000 mils