




- 1. Table of Contents (This Page)
 Created on Sat Feb 2 16:25:27 2013
- 2. component
- 3. solder
- 4. outline
- 5. plated-drill
- 6. componentmask
- 7. soldermask
- 8. topsilk
- 9. bottomsilk
- 10. toppaste
- 11. topassembly
- 12. bottomassembly
- 13. fab






























There are 7 different drill sizes used in this layout, 119 holes total

Symbol	Diam. (Inch)	Count	<u>Plated?</u>	
۲	0.020	29	YES	
+	0.028	8	YES	
×	0.030	14	YES	
۰	0.038	56	YES	Title: (unknown) - Fabrication Drawing
	0.048	4	YES	Author: Michael Petersen
\$	0.128	4	YES	Date: Sat 02 Feb 2013 11:25:27 PM GMT UTC
#	0.129	4	YES	



Board outline is the centerline of this path