




- 1. Table of Contents (This Page) Created on Mon Apr 8 21:49:42 2013
- 2. component
- 3. solder
- 4. plated-drill
- 5. componentmask
- 6. soldermask
- 7. topsilk
- 8. bottomsilk
- 9. toppaste
- 10. topassembly
- 11. bottomassembly
- 12. fab


























There are 9 different drill sizes used in this layout, 137 holes total

	9 SMT UTC તીક wide, 1998.888888 mils high	
	Title: (unknown) - Fabrication Drawing Author: Michael Petersen Date: Tue 89 Apr 2013 03:49:42 AM GMT UTC Maximum Dimensions: 3508.000808 mils wide, 1988.008080 mils high	
Plated? YES YES YES	YES YES YES	
Count 76 8 8 12 6 6	12 8 4 4	+
Diam. (Inch) Count 0.020 76 0.028 8 0.030 12 0.038 6	0.039 0.045 0.128 0.129	+ + + + + + + + + + + + + + + + + + +
Squabol + x °	□≽₩⊠⊚	◎