



- 1. Table of Contents (This Page) Created on Wed Jul 8 20:06:34 2015
- 2. top
- 3. bottom
- 4. outline
- 5. plated-drill
- 6. unplated-drill
- 7. componentmask
- 8. soldermask
- 9. topsilk
- 10. bottomsilk
- 11. toppaste
- 12. topassembly
- 13. bottomassembly
- 14. fab













•


•


















There are 7 different drill sizes used in this layout, 107 holes total

| Symbol | Diam. (Inch) Count | | Plated? | |
|--------|--------------------|----|---------|---|
| ۲ | 0.020 | 86 | YES | |
| + | 0.038 | 6 | YES | |
| × | 0.043 | 4 | YES | |
| ۰ | 0.048 | 2 | YES | Title: (unknown) - Fabrication Drawing |
| | 0.063 | 2 | N0 | Author: Michael Petersen |
| A | 0.075 | 3 | YES | Date: Thu 09 Jul 2015 02:06:34 AM GMT UTC |
| + | 0.129 | 4 | YES | |



Board outline is the centerline of this path