# EX.NO-2.1- CREATE A 3D SOLID MODEL FROM ISOMETRIC DRAWING

## AIM:

To create a 3D model from the given isometric drawing using a fusion 360 tool.

## REQUIREMENTS:

1. Autodesk fusion 360
2. Windows 10
3. 16 GB of RAM (integrated graphics recommend 2GB or more)
4. 2.5 Mbps or faster download; 500 Kbps or faster upload

## PROCEDURE:

1. First open your Autodesk fusion 360.


2. Select the new part design.

3. Open a new file and select the sketch icon.

4. Select the plane for sketching in front view.

5. Create a rectangle on the top plane using the Center Rectangle tool. Assign dimensions of 100mm x 60mm.

6. Select the finish sketch and extrude the rectangle and give it a thickness of 30mm.




7. Select the top surface to sketch a circle of 50mm diameter.


8. Extrude the circle with a dimension of 20mm.

9. Select the top surface of the rectangle and draw a small circle of 20mm diameter.


10. In the top of the rectangle draw a rectangle of dimensions 10mm x 10mm.

11. Extrude both the circle and the rectangle with a dimension of 15mm.

12. In the side of the rectangle surface draw a rectangle of dimension 30mm x 10mm.




13. Extrude the rectangle with a dimension of 10mm.




14. Add a line at the top of the big rectangle at an angle of 45 degrees to make it a triangle.


15. Extrude the triangle with a dimension of 30mm.


16. Apply appearances to the whole body with materials like gold or steel.

17. After finishing the sketch use the finish sketch option to finalize the sketch.





18. After extruding the sketch switch to drawing mode to plot the sketch in ISO standard.





CREATE DRAWING TEMPLATE
Base Document
Standard
ISO
Units
mm
Sheet Size
A3
Width
420mm
Height
297mm
Orientation
OK
Cancel
50

**SKETCHS:**


10.00
15.00
35.00
10.00
10.00
35.00
15.00
60.00
15.00
Ø20.00
15.00
Ø50.00
100.00

**OUTPUT:**




## RESULT:

Thus, the 3D model is created from the given isometric drawing.