

Inspection Report · VLV-501 2026 Q1

Gate valve VLV-501 (Velan) seat inspection: minor gasket weep consistent with FM-SEAL-03.
Recommend gasket replacement.