
Step in F1 (high noise)
Step in F2 (high noise)
y1 = h1 [cm]
y2 = h2 [cm]
time [min]
+10%
+25%
+50%
steady state