
(a) Risk aversion
(b) Hysteresis hold time
(c) Per-step change limit
Mission-success score
Reconfig. cost
Risk aversion ρ
Hold time T_h (s)
Max change per step Δ_{max} (PRBs)