Weinte New York + (\$16) | 271-6200 §arta Clara Clatifornia + 4081-385-24XX §ascartin Trangle Pain. North Carrina + 3131-349-1400 Clamas Washington + (36C) | 817-550X



POLIOLES S A DE C V
MR A H QUINTANILLA
FERNANDO MONTES DE OCA 71
COLONIA CONDESA
06140 MEXICO MEXICO



Your most recent listing is shown below. Please review this information and report any inaccuracies to the UL Engineering staff member who handled your UL project.

BRYX

Foamed Plastic

POLIOLES S A DE C V

April 2, 1997

R11205 (S)

(A1 - cont. from A card)

- Flame spread and smoke developed recorded while material remained in the original test position. Ignition of molten residue on furnace floor resulted in flame travel equivalent to calculated flame spread classification of 25 and smoke developed classification of over 500.

Styropor Types F0305, F0405, F0507, F0710, F1015, F1525, FR1015, FR0710, FR0507 or Styropor Types AF112, AF212, AF312, AF412 and AF512

Flame spread Smoke developed 2.5CM (1 In.) Max+ 5# 175# 5.1CK (2 In.) Kax+ 5## 175## 10.2CM (4 In.) Max+ Seff 175818

Replaces R11205A1 dated January 25, 1994. 585238001 H0897 Underwriters Laboratories Inc.®

(Cont. on \$ card) A11/0128153

For information on placing an order for UL Listing Cards in a 3 × 5 inch card format, please refer to the enclosed ordering information.

UNDERWRITERS LABORATORIES INC.

A not-for-profit organization dedicated to public safety and committed to quality service