



Twain Driver Release Notes

Subject:	Update
Model	Twain Driver v3.2

Twain Driver v3.2

Type	FILE Name	VER.	PJ	Remarks
Driver	Kyocera TWAIN Driver_3.2.0512	3.2.0512	TWAIN	

Details of Changes

No	Items	Contents
1	Model support (TWAIN Driver)	TWAIN Driver supports the following models. ECOSYS MA4000x, ECOSYS MA4000fx, ECOSYS MA4000wfx ECOSYS MA4000wifx, ECOSYS MA6000ifx, ECOSYS MA5500ifx, ECOSYS MA4500ifx, ECOSYS MA4500ix, ECOSYS MA4500fx, ECOSYS MA4500x, ECOSYS MA2100cwfx, ECOSYS MA2100cfx, ECOSYS MA2100cx, ECOSYS MA2600cwfx, ECOSYS MA2600cfx, ECOSYS MA2600cwx, ECOSYS MA2101cwfx, ECOSYS MA2101cfx, TASKalfa 4020i, TASKalfa 3060ci, TASKalfa MZ4000i, TASKalfa MZ3200i
2	Help message addition	The help message is now displayed when each button is hovered over.
3	Corrective measures for incorrect error message display	When DP is selected as the feed method and scanning is performed without correctly setting paper in the DP, the displayed error message is incorrect. This has been corrected.
4	Corrective measures for missing scan pages	The application might stop during scanning, causing scan pages to be missing. This has been corrected.
5	Unit default settings correction	In TWAIN Driver Settings, the default unit was always set to "Inch". It is corrected so that the default unit is changed according to the OS regional settings.
6	SSL default settings correction	In TWAIN Driver Settings, the default setting had SSL checkbox selected. It is corrected so that the default setting is changed to an unchecked state.
7	Corrective measures for TWAIN update failure (1)	The update of the TWAIN driver might fail. This has been corrected.
8	Corrective measures for TWAIN update failure (2)	If WIA is installed beforehand, the update of the TWAIN driver might fail. This has been corrected.
9	Corrective measures for communication failure	When scanning large data via USB connection, communication between the device and the PC might be lost. This has been corrected.
10	Correction of installation target models	When installing TWAIN driver in Product Library, printer models are displayed. Therefore, the printer models are excluded.
11	Corrective measures for TWAIN Driver version misdisplay	The version of TWAIN Driver when displayed when utilizing the Twacker application is incorrect. This has been corrected.



Twain Driver Release Notes

No	Items	Contents
12	Corrective measures for TWAIN Driver GDI version misdisplay	The version of the TWAIN Driver GDI displayed when utilizing the Twacker application is incorrect. This has been corrected.
13	Corrective measures for TWAIN Box version misdisplay	The version of TWAIN Box displayed when utilizing the Twacker application is incorrect. This has been corrected.
14	Correction of default resolution settings	The default resolution in TWAIN Driver GDI display might be incorrect. This has been corrected.
15	Corrective measures for checkbox behavior issues	In Quick Scan, clicking outside the text area of [Auto] checkbox for density settings causes the checkbox to be selected or deselected. This has been corrected.
16	Corrective measures for window size issues	When TWAIN Driver Settings window is dragged with the mouse, it is displayed at an incorrect window size. This has been corrected.
17	Correction of scanner list screen UI	In the scanner list screen of TWAIN Driver, some borders on UI are missing. This has been corrected.
18	Corrective measures for runtime errors	In TWAIN Driver Setting, if only the username is set while the password remains blank during authentication setup, a runtime error occurs when retrieving the TWAIN Driver when utilizing the Twacker application. This has been corrected.
19	Correction of about screen behavior	After displaying the about screen in TWAIN Driver Setting, clicking the TWAIN Driver Settings icon on the taskbar makes the about screen unclickable. This has been corrected.
20	Corrective measures for unit setting reflection issues	The unit setting changed in the TWAIN Driver Setting are not reflected in Quick Scan. This has been corrected.
21	Corrective measures for incorrect display of constraint errors (1)	In Quick Scan, when the color setting is set to black and white, attempting to set the contrast to anything other than [0] results in a constraint error being displayed. This has been corrected.
22	Corrective measures for incorrect display of constraint errors (2)	When TWAIN Driver is installed via USB connection, the error message displayed during a constraint error is incorrect. This has been corrected.

[CVE Reference No.] No CVE No. is supported this time.



Twain Driver Release Notes

Previous Updates

Twain Driver v3.1

Type	FILE Name	VER.	PJ	Remarks
Driver	Kyocera TWAIN Driver_3.1.0915c	3.1.0915	TWAIN	

Details of Changes

No	Items	Contents
1	Model support	The models below are newly supported. ECOSYS MA6000ifx, ECOSYS MA5500ifx, ECOSYS MA4500ifx, ECOSYS MA4500ix, ECOSYS MA4500fx, ECOSYS MA4500x TASKalfa MA4500ci, TASKalfa MA3500ci, ECOSYS MA4000cifx, ECOSYS MA4000cix, ECOSYS MA3500cifx, ECOSYS MA3500cix
2	TWAIN GDI support	The installation of TWAIN GDI is supported.
3	OS support	ARM64 is supported. [Support OS] - Windows 10 (32bit, 64bit, ARM64) - Windows 11 (64bit, ARM64) - Windows Server 2016 (64bit) - Windows Server 2019 (64bit) - Windows Server 2022 (64bit)
4	Support for new branding	TWAIN Driver and Quick Scan are updated to support the new branding.
5	Support of the device detection feature	The device detection feature is supported.
6	Support of UTF-8 (3 byte/4 byte)	UTF-8 3 byte/4 byte is supported.
7	Correcting the display	The display of driver names (uppercase/lowercase) in TWAIN Driver and Quick Scan is standardized. Additionally, the phrase 'The New Value Frontier' from the dialog" is removed.
8	Scan orientation support	Quick Scan now supports all scan orientations.
9	1200dpi support	Quick Scan now supports 1200dpi resolutions.



Twain Driver Release Notes

No	Items	Contents
10	UI changes	The following UI is modified in Quick Scan. - The position of some buttons are misaligned when a custom profile is selected. This has been corrected. - The icon color does not change when selecting the new profile addition icon. This has been corrected. - The UI display is unified. - The size of some icons is unified.
11	Correcting the background color	After the PC returns from the sleep mode, the background color of the TWAIN Driver becomes white. This has been corrected.



Twain Driver Release Notes

Previous Updates

Type	FILE Name	VER.	PJ	Remarks
Driver	TWAIN 3.0 Webpackage KM RC8	3.0.5615	TWAIN	

Details of Changes

No.	Items	Contents
1	Copyright update	The copyright is changed to 2022.
2	Support of 1200 dpi	1200 dpi is newly supported.
3	Windows11 support	Windows11 is newly supported.
4	Corrective measure for the problem that a value which exceeds the maximum compression level can be input	Although the maximum value of the compression level (Gray/Monochrome) is "5" on the driver setting of TWAIN, a value with 2 digits can be input. Also, if 5 or more is input, no error is displayed.
5	Corrective measure for the failures when deleting the custom profile	When the custom profile is deleted, the following phenomena might occur. [Phenomena] 1. Although the custom profile is not selected, the delete button is available. (The delete button is not grayed-out.) 2. Although [OK] button is selected on the confirmation screen for deleting the profile, the profile is not deleted.
6	Corrective measure for the failure of the profile dialog	Although [X] or [cancel] button is not clicked on the profile dialog, the dialog closes when double-clicking any area inside the setting screen.
7	Corrective measure for the problem that the input account ID is displayed as asterisk (*)	When the account ID is activated on the user authentication setting and an ID is input, the ID is displayed as asterisk (*) although the specification allows the user to see the input ID.
8	Corrective measure for the freeze and the inability to use the quick scan under the multi-user environment	When using the quick scan under the multi-user environment, the following phenomena occur. Thus, this update enables the quick scan under the multi-user environment. 1. When the user with the local authorization installs the quick scan and logs out, and then the user without local authorization logs in, the device settings on the TWAIN driver is deleted. 2. When the user who has not logged in at the installation of TWAIN uses the quick scan, TWAIN freezes during the scan.
9	Corrective measure for the failure of the status bar on the scan preview screen	When selecting any area inside the image on the scan preview screen, the size of the selected area is not displayed on the status bar.
10	Model support	The models listed are newly supported.

*See the followings for the support models and OS.

KYOCERA Document Solutions America, Inc.



Twain Driver Release Notes

Support models

Models
TASKalfa 7054ci
TASKalfa 6054ci
TASKalfa 5054ci
TASKalfa 4054ci
TASKalfa 3554ci
TASKalfa 2554ci
TASKalfa 7004i
TASKalfa 6004i
TASKalfa 5004i
TASKalfa 4004i
TASKalfa 6053ci
TASKalfa 5053ci
TASKalfa 4053ci
TASKalfa 3553ci
TASKalfa 3253ci
TASKalfa 2553ci
TASKalfa 6003i
TASKalfa 5003i
TASKalfa 4003i
TASKalfa MZ4000i
TASKalfa MZ3200i
TASKalfa 4012i
TASKalfa 3212i
TASKalfa 8353ci
TASKalfa 7353ci
TASKalfa 9003i
TASKalfa 8003i
TASKalfa 7003i

Models
ECOSYS M4132idn
ECOSYS M4125idn
TASKalfa 2520i
TASKalfa 2510i
ECOSYS M4230idn
ECOSYS M4226idn
ECOSYS M8130cidn
ECOSYS M8124cidn
TASKalfa 2470ci
TASKalfa 2460ci
ECOSYS M8228cidn
ECOSYS M8224cidn
TASKalfa 508ci
TASKalfa 408ci
TASKalfa 358ci
TASKalfa 308ci
TASKalfa 307ci
ECOSYS M6635cidn
ECOSYS M6235cidn
ECOSYS M6630cidn
ECOSYS M6230cidn
TASKalfa 352ci
TASKalfa 351ci
ECOSYS M3660idn
ECOSYS M3655idn
ECOSYS M3645idn
ECOSYS M3145idn
ECOSYS M3645dn
ECOSYS M3145dn

Models
ECOSYS M3860idnf
ECOSYS M3860idn
ECOSYS M5526cdn
ECOSYS M5526cdw
ECOSYS M5521cdw
ECOSYS M5520cdw
ECOSYS M5525cdn
ECOSYS M5521cdn
ECOSYS M5520cdn
ECOSYS M5021cdn
ECOSYS MA2100cwfx
ECOSYS MA2100cfx
ECOSYS MA2100cx
ECOSYS M2640idw
ECOSYS M2735dw
ECOSYS M2635dw
ECOSYS M2540dw
ECOSYS M2635dn
ECOSYS M2540dn
ECOSYS M2040dn
ECOSYS M2135dn
ECOSYS M2835dw
ECOSYS M2735dn
ECOSYS M2235dn



Twain Driver Release Notes

Supported CopyStar Models

Models
CS 7054ci
CS 6054ci
CS 5054ci
CS 4054ci
CS 3554ci
CS 2554ci
CS 7004i
CS 6004i
CS 5004i
CS 4004i
CS 6053ci
CS 5053ci
CS 4053ci
CS 3553ci
CS 3253ci
CS 2553ci
CS 6003i
CS 5003i
CS 4003i

Models
CS MZ4000i
CS MZ3200i
CS 4012i
CS 3212i
CS 8353ci
CS 7353ci
CS 9003i
CS 8003i
CS 7003i
CS 508ci
CS 408ci
CS 358ci
CS 308ci
CS 307ci

[Support OS]

OS
Windows 8.1
Windows 10
Windows 11
Windows Server 2012/R2, 2016